

Statistical mapping of USPC to CPC for Class 264

| USPC Subclass | Most statistically relevant CPC groups |
|---------------|---|
| 264/0.5 | Y 02E 30/38, G 21C 3/623, G 21C 3/62, G 21C 21/02, G 21C 3/64 |
| 264/1.1 | B 29L 2011/0016, B 29D 11/00413, B 29D 11/00432, B 29K 2105/0002, B 29L 2011/0041 |
| 264/1.21 | G 02B 1/02, C 04B 35/115, C 03B 19/12, C 04B 35/547, C 04B 35/64 |
| 264/1.22 | C 04B 35/505, G 01T 1/2023, C 04B 35/645, C 04B 35/50, C 04B 35/6455 |
| 264/1.23 | G 02B 1/02, H 01S 3/034, C 03B 2201/84, C 01F 5/28, C 03B 37/023 |
| 264/1.24 | B 29D 11/00663, B 29D 11/00721, B 29L 2011/0075, G 02B 6/138, G 02B 6/1221 |
| 264/1.25 | G 02B 6/3865, B 29D 11/0075, B 29L 2011/0075, G 02B 6/3885, B 29D 11/00663 |
| 264/1.26 | A 61F 2002/1686, B 29C 39/10, B 29C 65/1416, B 29C 65/1435, B 29C 65/1483 |
| 264/1.27 | B 29D 11/00663, B 29C 47/00, B 29C 2035/0827, G 02B 6/1221, B 29C 35/10 |
| 264/1.28 | B 29C 47/027, B 29D 11/00663, G 02B 6/4479, G 02B 6/4483, G 02B 6/4484 |
| 264/1.29 | B 29C 47/00, B 29D 11/00663, B 29L 2011/0075, B 29D 11/00721, G 02B 6/02038 |
| 264/1.31 | B 29L 2031/7224, G 02B 5/1852, B 29C 45/372, B 29D 11/00, B 29L 2011/00 |
| 264/1.32 | B 29L 2011/0016, B 29D 11/00413, B 29D 11/00009, B 29D 11/0073, B 29D 11/00528 |
| 264/1.33 | B 29D 17/005, G 11B 7/26, G 11B 7/263, B 29L 2017/005, B 29C 45/263 |
| 264/1.34 | G 02B 5/3033, C 08J 5/18, B 29K 2995/0034, G 02B 5/3083, B 29C 55/06 |
| 264/1.35 | G 02B 5/3033, B 29K 2995/0034, G 02B 1/04, B 29D 7/01, C 08J 5/18 |

| | |
|----------|--|
| 264/1.36 | B 29C 2035/0827, B 29L 2011/0016, B 29D 11/00442, B 29K 2105/0002, B 29L 2011/0041 |
| 264/1.37 | A 61F 2002/1686, A 61F 2/16, B 29C 2035/0838, B 29L 2011/0016, B 29C 65/16 |
| 264/1.38 | B 29C 2035/0827, B 29C 35/0888, B 29D 11/00442, B 29C 2791/001, B 29D 11/00413 |
| 264/1.6 | B 29C 59/04, B 29K 2995/003, B 29C 43/222, B 29L 2011/00, B 29L 2011/0091 |
| 264/1.7 | B 29L 2011/0016, B 29D 11/0073, B 29D 11/00009, B 29D 11/00317, B 29D 11/023 |
| 264/1.8 | B 29D 11/00028, B 29D 11/00932, B 29L 2011/0016, G 02C 7/06, B 29D 11/00942 |
| 264/1.9 | B 29L 2011/0083, B 29D 11/00596, B 29D 11/00605, E 01F 9/06, G 02B 5/124 |
| 264/2.1 | B 29C 41/045, B 29L 2011/0041, B 29K 2105/0002, B 29D 11/00115, B 29L 2031/76 |
| 264/2.2 | B 29L 2011/0016, B 29C 45/561, B 29D 11/00413, B 29C 33/0038, B 29D 11/00528 |
| 264/2.3 | B 29D 11/00413, B 29D 11/00125, B 29D 11/00528, B 29C 33/0038, B 29D 11/00009 |
| 264/2.4 | B 29D 11/00009, B 29C 43/021, B 29L 2011/0016, B 29C 43/00, B 29C 2043/3618 |
| 264/2.5 | B 29L 2011/0016, B 29C 33/3842, B 29D 11/00125, B 29D 11/00432, B 29D 11/00278 |
| 264/2.6 | G 02B 1/043, B 29D 11/00067, B 29C 71/0009, B 29L 2011/0041, B 29D 11/00038 |
| 264/2.7 | B 29D 11/0073, B 29D 11/023, G 02C 7/12, B 29K 2033/12, B 29L 2011/0016 |
| 264/3.1 | C 06B 21/0058, F 02K 9/24, C 06B 21/0041, C 06B 21/0025, C 06B 45/10 |
| 264/3.2 | C 06B 21/0041, C 06B 21/0008, C 06B 21/0075, C 06B 21/0033, C 06B 45/12 |
| 264/3.3 | C 06B 21/0075, C 06B 21/0008, C 06B 45/10, C 06B 21/0025, B 30B 11/24 |
| 264/3.4 | C 06B 21/0066, C 06B 21/0041, C 06B 21/0083, |

| | |
|----------|---|
| | C 06B 31/28, C 06D 5/06 |
| 264/3.5 | C 06B 21/0066, C 06B 21/0091, B 01J 2/06, C 06B 21/00, C 06B 21/005 |
| 264/3.6 | C 06B 21/0066, C 06B 45/12, C 06B 21/0091, C 06B 21/0008, C 06B 21/0025 |
| 264/4 | A 61J 3/07, B 01J 13/04, A 61K 9/5089, A 61K 9/1694, A 61K 48/00 |
| 264/4.1 | B 01J 13/02, A 61K 9/1277, B 01J 13/04, B 01J 13/16, B 01J 13/18 |
| 264/4.3 | A 61K 9/1277, B 01J 13/10, B 01J 13/20, B 01J 13/206, A 61K 9/5089 |
| 264/4.32 | A 61K 9/5089, A 61J 3/07, A 61K 8/11, A 61K 9/1271, A 61K 9/1272 |
| 264/4.33 | B 01J 13/14, B 01J 13/18, B 01J 13/02, B 41M 5/165, B 01J 13/043 |
| 264/4.4 | B 01J 13/04, B 01J 13/10, B 41M 5/165, A 61J 3/07, A 61K 9/50 |
| 264/4.6 | A 61K 9/1277, A 61K 9/1694, A 61K 9/1647, B 01J 13/12, B 01J 13/125 |
| 264/4.7 | B 01J 13/18, B 41M 5/165, B 01J 13/16, B 01J 13/02, B 01J 13/185 |
| 264/5 | A 61K 9/1694, Y 02E 30/38, A 61K 9/1647, B 01J 2/04, A 61K 9/1688 |
| 264/6 | D 04H 1/565, D 01D 5/0985, D 01D 5/18, D 04H 3/16, D 04H 1/56 |
| 264/7 | B 01J 2/04, B 01J 2/16, B 01J 2/02, C 01P 2004/61, B 01J 2/003 |
| 264/8 | D 01D 5/18, B 01J 2/04, B 22F 9/10, C 03B 19/1015, A 23G 3/10 |
| 264/9 | B 01J 2/04, B 01J 2/06, B 22F 9/08, B 01J 2/02, B 01J 2/08 |
| 264/10 | D 01D 5/0076, D 01D 5/0092, D 01D 5/0069, B 82Y 30/00, D 01D 5/0007 |
| 264/11 | B 01J 2/06, D 01D 5/40, B 01J 2/04, B 22F 9/082, B 22F 2009/0828 |

| | |
|---------|---|
| 264/12 | B 01J 2/04, B 22F 9/082, D 01D 5/0985, D 01D 5/11, D 04H 1/565 |
| 264/13 | D 01D 5/11, B 01J 2/04, B 01J 2/06, B 01J 2/02, B 22F 9/08 |
| 264/14 | B 01J 2/04, C 05C 9/005, B 01J 2/06, B 01J 2/16, B 01J 2/02 |
| 264/15 | C 01P 2004/32, C 08J 3/12, B 01J 2/20, C 01P 2004/61, B 01J 2/12 |
| 264/16 | A 61C 13/0003, A 61K 6/06, A 61C 13/20, A 61K 6/033, A 61C 13/0004 |
| 264/17 | A 61C 13/00, A 61C 13/04, A 61C 13/20, A 61K 6/083, A 61C 13/0025 |
| 264/18 | A 61C 13/04, A 61C 13/00, A 61C 13/0001, A 61C 13/16, A 61K 6/083 |
| 264/19 | A 61C 13/0003, A 61C 13/081, A 61C 5/10, A 61K 6/06, A 61K 6/083 |
| 264/20 | A 61C 13/081, A 61C 13/08, A 61C 13/082, A 61C 13/0022, A 61C 13/206 |
| 264/21 | G 21K 4/00, A 43B 3/0084, C 09K 11/02, C 09K 11/616, G 01N 21/64 |
| 264/400 | B 23K 26/4065, B 29C 2035/0838, B 23K 26/381, B 23K 26/0656, B 29C 59/16 |
| 264/401 | B 29C 67/0066, B 29C 67/0092, G 03F 7/0037, B 29K 2995/0073, G 05B 2219/49013 |
| 264/402 | B 29C 35/045, B 29C 33/06, B 29C 33/36, B 29C 35/04, B 29C 35/0805 |
| 264/403 | B 29C 33/06, B 29C 2035/0811, B 29C 45/73, B 29C 2035/0816, B 29C 33/04 |
| 264/404 | B 29C 33/02, B 29C 2035/0211, B 29C 33/06, B 29C 33/38, B 29C 35/02 |
| 264/405 | B 29C 47/903, B 22F 3/1055, B 22F 2998/00, B 29C 33/08, B 29C 35/12 |
| 264/406 | B 27N 3/18, B 29C 35/0288, B 29C 2035/0833, A 61C 19/003, B 29B 13/00 |
| 264/407 | B 29C 47/92, B 29C 2947/92428, B 29C |

| | |
|---------|--|
| | 2947/92647, B 29C 2947/92923, B 29C 2947/92152 |
| 264/408 | B 29C 47/92, B 29C 2947/92647, G 05D 5/03, H 01B 13/146, B 29C 35/0288 |
| 264/409 | B 29C 47/92, B 29C 2947/92152, B 29C 2947/92428, B 29C 2947/92438, B 29C 2947/9258 |
| 264/410 | B 29C 49/06, B 29C 47/92, B 29C 49/78, B 29C 49/80, G 01N 21/9081 |
| 264/411 | B 29C 47/92, B 29C 44/60, B 29C 2947/92428, B 29C 2947/92923, B 29C 47/8815 |
| 264/412 | B 29C 47/92, B 29C 2947/92428, B 29C 2947/9258, B 29C 2947/92904, B 29C 2947/92123 |
| 264/497 | B 29C 67/0077, B 22F 3/1055, B 23K 26/34, G 05B 2219/49013, B 22F 3/004 |
| 264/413 | B 29K 2105/04, B 29C 44/5636, B 01D 69/02, B 29C 67/20, B 01D 67/0011 |
| 264/414 | Y 02E 60/12, B 22F 2998/00, B 28B 1/50, B 29C 47/0019, B 29C 47/065 |
| 264/415 | B 29C 35/12, B 29C 35/02, B 29C 44/005, B 29C 44/0407, B 29C 44/146 |
| 264/416 | B 29C 67/2235, B 29C 67/2295, B 29C 2791/008, B 29K 2023/12, B 29K 2025/00 |
| 264/417 | B 29C 44/3415, B 29C 2035/0855, C 08J 2379/08, B 29C 33/06, B 29C 35/08 |
| 264/418 | C 08J 9/224, C 08J 9/232, C 08J 9/30, B 29C 33/0033, B 29C 33/06 |
| 264/419 | C 08J 9/06, B 29C 44/588, B 29L 2031/3005, C 08J 2323/28, A 61F 11/10 |
| 264/420 | B 29C 2035/0855, B 29C 35/08, B 29C 47/8805, B 29K 2021/00, B 29K 2105/04 |
| 264/421 | B 29C 33/10, B 29C 33/405, B 29C 35/08, B 29C 44/3415, B 29B 13/02 |
| 264/422 | B 29K 2021/00, B 29C 33/06, B 29C 35/12, B 29C 44/3415, C 08J 9/36 |

| | |
|---------|---|
| 264/423 | B 01D 67/009, B 03C 3/28, B 29C 59/10, B 01D 71/42, B 29C 67/202 |
| 264/424 | B 01D 67/0006, A 61J 3/07, A 61K 9/0039, A 61K 9/4808, A 61K 9/4816 |
| 264/425 | B 01D 67/003, B 01D 67/0006, B 01D 69/141, C 08J 9/141, C 08J 9/26 |
| 264/426 | B 28B 1/52, B 28B 1/0873, B 28B 7/42, B 28B 11/242, C 04B 28/02 |
| 264/427 | H 01F 41/0273, C 04B 35/2683, H 01F 41/028, B 28B 1/265, H 01F 13/003 |
| 264/428 | C 04B 35/2683, C 04B 35/26, H 01F 1/113, H 01F 41/0273, B 22F 3/02 |
| 264/429 | B 29K 2995/0008, B 29C 45/0013, H 01F 41/0273, H 01F 41/028, H 01F 1/0558 |
| 264/430 | C 04B 41/009, C 04B 35/486, C 04B 35/64, H 01L 41/39, B 22F 2998/00 |
| 264/431 | C 04B 35/573, C 04B 35/64, C 04B 35/645, B 22D 11/005, B 22D 11/0611 |
| 264/432 | C 04B 35/64, H 05B 6/80, B 28B 11/243, C 04B 35/584, C 04B 2235/667 |
| 264/433 | C 04B 35/571, C 04B 33/30, C 04B 35/62227, B 22D 11/005, B 23K 26/0621 |
| 264/434 | C 04B 35/645, C 04B 35/64, C 04B 2235/77, B 82Y 30/00, C 04B 2235/666 |
| 264/435 | H 01L 41/45, H 01L 37/02, H 01L 37/025, B 29C 55/005, B 29C 71/0081 |
| 264/436 | H 01G 7/023, B 01D 39/1623, B 01D 2239/10, B 29C 71/0081, B 01D 39/083 |
| 264/437 | B 29C 70/62, B 29C 39/006, H 01R 13/2414, B 22D 27/02, B 22F 3/004 |
| 264/438 | B 27N 3/143, B 29K 2021/00, B 29C 70/14, B 05C 19/002, B 29B 11/16 |
| 264/439 | B 29C 41/006, B 29C 41/08, B 29C 70/62, B 05B 5/08, B 05D 1/06 |
| 264/440 | B 29C 37/0032, B 29C 41/006, B 29C 2037/0039, |

| | |
|---------|---|
| | B 29K 2101/10, B 29K 2105/16 |
| 264/441 | D 01D 5/11, D 04H 3/16, A 61F 2/06, B 05D 1/16, B 29C 70/12 |
| 264/442 | B 29C 2791/008, B 29C 35/0261, B 29K 2021/00, B 26D 7/086, B 26F 1/26 |
| 264/443 | B 29C 2791/008, B 29C 35/0261, B 29C 45/568, B 29C 65/08, B 29K 2105/251 |
| 264/444 | B 29C 47/0071, B 29B 15/122, B 29C 47/0026, B 29C 47/54, B 29C 2791/008 |
| 264/445 | B 29C 65/08, B 29L 2005/00, A 44B 19/60, A 44B 19/36, B 29C 66/47 |
| 264/446 | B 29C 59/16, B 29C 2035/0827, B 29C 59/005, B 29C 59/10, B 29C 2035/0822 |
| 264/447 | B 05D 3/067, B 29C 2035/0827, B 29K 2021/00, B 32B 3/02, B 32B 27/06 |
| 264/448 | B 29C 59/16, B 29C 2035/0827, B 29C 59/10, B 29K 2067/00, C 08J 7/123 |
| 264/449 | B 29C 35/12, B 29C 65/34, B 29C 66/1122, B 29L 2030/00, B 29C 35/14 |
| 264/450 | B 29C 35/12, B 29K 2021/00, B 29C 61/003, B 29C 61/0625, B 29C 65/68 |
| 264/451 | B 29C 35/12, B 27N 3/203, B 29C 65/04, C 04B 35/532, C 08L 97/02 |
| 264/452 | C 04B 35/532, B 22F 3/105, B 29C 47/0004, B 82Y 30/00, C 04B 33/32 |
| 264/453 | B 29C 45/72, B 29C 51/10, B 29C 51/267, B 29C 65/04, B 29C 66/3282 |
| 264/454 | B 29C 49/06, B 29C 2035/0822, B 29K 2023/12, B 29K 2067/00, B 29B 2911/1402 |
| 264/455 | A 61F 13/00991, A 61F 13/15731, A 61F 13/512, B 26F 1/26, B 29C 59/10 |
| 264/456 | B 29C 61/08, B 29C 47/0023, C 08J 2323/08, B 29C 47/0026, B 29C 61/003 |
| 264/457 | B 29C 49/64, B 29C 49/6409, B 29C 71/0063, B 29C 71/02, B 29C 2035/0811 |

| | |
|---------|---|
| 264/458 | B 29C 2035/0822, B 29C 49/06, B 29K 2067/00, B 29C 49/649, B 29C 35/08 |
| 264/459 | B 29C 2035/0827, B 29C 70/443, B 29K 2021/00, A 61B 5/14542, A 61B 5/1473 |
| 264/460 | B 29C 67/0077, B 29C 67/0081, B 29C 67/04, B 29C 2035/0827, B 22F 3/004 |
| 264/461 | B 01J 20/28028, B 01J 20/28033, B 27N 3/00, B 27N 3/002, B 29C 67/04 |
| 264/462 | A 61K 9/1617, A 61K 9/1694, B 01D 39/1623, B 01D 39/2006, B 01D 69/10 |
| 264/463 | B 29C 67/0081, B 29C 2035/0827, B 29C 2035/0855, B 28B 1/00, B 28B 1/001 |
| 264/464 | D 01F 6/06, B 01D 39/1623, B 01D 2239/0435, B 01D 2239/0622, B 01D 2239/064 |
| 264/465 | D 01D 5/0038, D 01D 5/0069, D 01D 5/0092, D 01D 5/0076, D 04H 3/16 |
| 264/466 | B 29C 47/887, B 29C 47/8845, B 29K 2067/00, B 29C 47/0021, C 08J 5/18 |
| 264/467 | B 29C 47/887, B 29C 71/00, B 29D 7/00, B 29C 47/888, B 29C 55/04 |
| 264/468 | B 29C 47/887, B 29C 47/8855, A 61F 13/15, A 61F 13/15731, A 61F 13/5121 |
| 264/469 | B 32B 27/32, C 08L 23/06, B 29C 59/10, B 32B 37/153, C 08L 2205/03 |
| 264/470 | B 29C 2035/0877, C 08J 7/18, C 04B 35/571, C 08J 3/28, C 08J 5/18 |
| 264/471 | B 29K 2023/06, B 32B 27/08, B 32B 27/32, B 29C 35/08, B 29C 55/023 |
| 264/472 | H 05B 6/105, A 61M 25/0009, B 26D 3/02, B 26D 7/084, B 26D 7/10 |
| 264/473 | B 29C 71/04, B 29K 2105/243, A 01K 91/00, A 61L 15/12, A 61L 27/16 |
| 264/474 | B 29C 2035/0855, B 29C 47/0023, B 29D 23/001, B 29K 2021/00, B 29C 35/10 |
| 264/475 | B 29C 47/00, B 29B 11/04, B 29B 11/12, B 29B |

| | |
|---------|--|
| | 11/14, B 29B 13/023 |
| 264/476 | B 29C 55/06, B 29K 2067/00, B 29C 43/24, B 29C 55/065, B 29C 55/18 |
| 264/477 | B 29C 35/10, B 29C 47/065, B 29C 2035/0827, B 29C 47/0004, B 29C 47/0019 |
| 264/478 | B 29C 45/00, B 29C 45/0053, B 29C 45/14065, B 29C 2035/0827, B 29C 2035/0877 |
| 264/479 | B 29C 71/02, B 29C 2035/085, B 29L 2031/7532, A 61F 2/3094, A 61F 2/389 |
| 264/480 | B 29C 35/08, B 29C 55/023, B 29B 13/08, B 01D 39/1623, B 29B 9/16 |
| 264/481 | B 29C 35/02, B 29C 2035/0822, B 29K 2067/00, B 29C 55/00, B 29C 55/08 |
| 264/482 | B 29C 2035/0838, B 29C 59/16, B 29C 65/16, B 29C 66/1122, A 61M 25/0009 |
| 264/483 | B 29C 59/14, B 29C 59/142, B 29C 59/16, B 29C 2035/0827, H 01T 19/00 |
| 264/484 | B 29C 47/887, B 29C 71/0081, H 05F 3/04, B 01D 2239/065, B 03C 3/28 |
| 264/485 | B 29C 71/04, B 29C 2035/0877, B 29C 35/08, B 29K 2023/06, A 61L 27/16 |
| 264/486 | B 29C 2035/0811, B 29C 35/0272, B 29C 35/08, B 29C 2035/0861, B 29C 33/06 |
| 264/487 | B 29C 2035/0811, B 29C 35/0272, B 29C 35/08, B 29K 2021/00, B 29K 2707/04 |
| 264/488 | B 29C 2035/085, B 29C 2035/0877, B 29C 35/08, C 08L 2312/06, A 61F 2/3094 |
| 264/489 | B 29C 2035/0855, B 29C 33/52, B 29C 35/08, H 05B 6/80, B 22C 1/167 |
| 264/490 | B 29C 2035/0855, B 29C 35/08, B 29C 35/12, B 29C 70/80, B 29K 2027/06 |
| 264/491 | B 29C 35/12, B 29K 2027/06, B 29C 33/02, B 29C 43/52, B 29K 2021/00 |
| 264/492 | B 29C 2035/0822, B 29C 71/02, B 29L 2031/7158, B 29C 37/0057, B 29C 71/04 |

| | |
|----------|--|
| 264/493 | B 29C 2035/0822, B 29C 35/0288, B 29C 35/08, B 29C 65/14, B 29C 65/1412 |
| 264/494 | B 29C 2035/0827, C 08F 2/48, C 08L 2312/06, B 29C 67/0059, B 82Y 30/00 |
| 264/495 | B 29C 2035/0827, B 29B 15/122, C 08F 20/10, B 29B 9/14, B 29C 35/10 |
| 264/496 | B 29C 2035/0827, G 03F 7/0002, B 82Y 10/00, B 29C 35/0888, B 29K 2105/0002 |
| 264/28 | C 08J 9/28, B 22F 3/222, B 28B 1/007, B 29C 35/16, C 08J 5/18 |
| 264/29.1 | C 04B 35/83, C 04B 35/532, C 04B 35/573, C 04B 38/0022, C 04B 35/524 |
| 264/29.2 | D 01F 9/145, D 01F 9/22, C 04B 35/83, B 82Y 30/00, D 01F 9/00 |
| 264/29.3 | C 04B 35/532, C 01B 31/00, C 04B 35/52, B 01J 2/28, C 01B 31/36 |
| 264/29.4 | C 04B 35/524, H 01G 9/155, H 01M 4/96, Y 02E 60/50, C 01B 31/00 |
| 264/29.5 | C 04B 35/83, F 16D 69/023, C 04B 35/532, C 04B 2235/77, C 04B 35/522 |
| 264/29.6 | C 04B 35/524, C 04B 35/532, C 04B 35/83, C 04B 35/565, H 01M 4/96 |
| 264/29.7 | C 04B 35/532, C 04B 35/573, C 04B 38/0022, C 01B 31/00, C 04B 35/565 |
| 264/30 | F 27D 1/16, F 27D 1/1626, F 27D 1/0006, F 27D 1/1642, B 22D 41/023 |
| 264/31 | E 04G 13/02, C 04B 40/04, E 04F 15/12, E 01C 7/147, E 04B 2/723 |
| 264/32 | E 04G 11/04, E 04H 7/18, E 04B 1/3211, E 04B 2001/3217, E 04B 2001/3264 |
| 264/33 | E 04G 11/22, B 28B 1/084, E 04G 11/28, B 28B 3/228, E 01D 2101/26 |
| 264/34 | E 01C 7/16, E 04B 2/84, E 04B 1/3505, E 04F 15/12, E 04G 11/00 |
| 264/35 | F 16L 55/1645, B 28B 19/0023, E 04G 17/06, E |

| | |
|-----------|---|
| | 04G 23/0203, F 16L 55/1654 |
| 264/36.1 | B 24D 3/346, B 29C 73/02, B 29C 73/025, B 29C 73/26, B 29C 73/30 |
| 264/36.11 | B 29C 73/06, B 29K 2075/00, A 47C 5/125, B 01D 37/00, B 01D 41/00 |
| 264/36.12 | B 29L 2031/54, A 63B 45/00, A 63B 47/00, A 63B 2243/0029, B 29B 17/02 |
| 264/36.13 | G 11B 3/66, G 11B 3/00, G 11B 3/58, G 11B 25/02 |
| 264/36.14 | B 29D 30/54, B 29L 2030/00, B 29C 35/049, B 29C 73/30, B 29C 73/06 |
| 264/36.15 | A 01K 85/00, B 01D 63/022, B 01D 65/104, B 01D 65/106, B 01D 65/108 |
| 264/36.16 | F 16L 55/175, E 03F 3/06, E 03F 2003/065, F 16L 55/164, A 22C 13/0003 |
| 264/36.17 | F 16L 55/1651, F 16L 55/1654, B 29C 63/36, B 29C 63/34, F 16L 55/1656 |
| 264/36.18 | B 29C 73/02, B 23K 35/34, B 29C 33/3857, B 29C 33/40, B 29C 33/424 |
| 264/36.19 | B 29C 73/10, E 04G 23/0218, H 01B 7/285, H 02G 1/145, H 02G 1/16 |
| 264/36.2 | E 04G 23/0203, A 01K 1/0151, A 01K 43/00, A 63D 9/00, B 05C 17/002 |
| 264/36.21 | B 29C 73/025, B 32B 17/10963, C 03C 17/32, B 29C 37/006, B 29L 2031/778 |
| 264/36.22 | B 29C 73/02, A 63D 9/00, A 43B 21/00, A 43D 95/06, A 43D 95/26 |
| 264/37.1 | B 29C 33/3821, B 29B 17/0042, B 29C 33/308, B 29C 33/38, B 29C 43/021 |
| 264/37.11 | B 01J 3/04, B 29C 47/882, B 29C 47/8835, B 29C 47/8845, B 29C 47/903 |
| 264/37.12 | B 29D 7/01, D 01D 5/04, D 01D 5/08, D 01D 5/247, D 01F 2/28 |
| 264/37.13 | D 01D 5/04, D 01F 6/04, D 01F 13/04, B 01D 11/0203, B 22F 3/1025 |

| | |
|-----------|--|
| 264/37.14 | B 29D 30/0601, B 29D 2030/0675, B 29K 2021/00, B 29L 2030/00, B 01D 19/0005 |
| 264/37.15 | B 29C 44/5609, B 29C 35/16, B 29C 44/3461, B 29C 44/386, B 29C 44/60 |
| 264/37.16 | B 29C 49/04, B 29C 49/66, B 29C 49/783, B 29C 49/06, B 29C 49/36 |
| 264/37.17 | B 29C 45/7207, B 29B 13/023, B 29C 35/16, B 29C 47/0893, B 29K 2105/253 |
| 264/37.18 | B 29C 41/18, C 07C 51/313, A 01J 21/02, A 45D 40/0087, A 45D 40/16 |
| 264/37.19 | B 28B 7/46, C 04B 28/04, A 01N 25/08, B 09B 3/0066, B 22D 7/108 |
| 264/37.2 | D 01F 2/00, D 01F 13/02, A 22C 13/0013, B 29C 47/92, B 29C 2947/92209 |
| 264/37.21 | D 01F 6/18, C 08J 3/095, C 08J 2351/00, C 08K 5/109, D 01D 10/0436 |
| 264/37.22 | D 01F 13/02, D 01F 2/28, D 01F 6/18, D 01D 5/06, B 01D 9/0022 |
| 264/37.23 | D 01F 2/04, C 01G 3/14, D 01F 6/18, D 01F 13/00, D 01F 13/04 |
| 264/37.24 | B 29C 47/0057, B 29B 9/08, B 29B 9/10, B 29C 35/065, B 29C 47/0021 |
| 264/37.25 | B 29C 49/46, B 29C 2049/4635, B 29C 2049/465, B 29C 2049/4652, B 29K 2067/00 |
| 264/37.26 | B 29C 47/0004, B 29C 47/38, B 29C 47/725, B 29C 47/92, B 29C 2947/92704 |
| 264/37.27 | B 29B 17/0026, B 29B 2017/0203, B 29C 45/0001, B 29C 47/00, B 29K 2023/0625 |
| 264/37.28 | B 29B 17/0026, B 29K 2105/26, C 03C 1/002, C 03C 1/026, C 08J 11/06 |
| 264/37.29 | B 01J 2/12, C 22B 1/2406, B 01J 2/14, B 01J 2/22, B 27N 3/14 |
| 264/37.3 | B 29C 43/22, B 29C 43/24, B 29K 2021/00, C 08K 3/08, C 08L 67/02 |
| 264/37.31 | B 29K 2067/00, B 29B 2911/1412, B 29B |

| | |
|-----------|---|
| | 2911/14126, B 29C 49/04, B 29C 49/06 |
| 264/37.32 | B 29B 17/0005, B 29C 47/0019, B 29C 47/0021, B 29C 47/065, B 29C 47/10 |
| 264/37.33 | B 29C 2045/386, B 29B 17/0005, B 29C 44/105, B 29C 45/38, B 29B 11/06 |
| 264/39 | B 29C 33/72, B 29C 45/1753, B 29K 2075/00, B 29C 45/14655, B 29C 47/0877 |
| 264/40.1 | B 29C 45/76, B 29C 45/77, B 29C 47/92, B 29C 2945/76006, B 29C 2947/92904 |
| 264/40.3 | B 29C 47/92, B 29C 47/0026, B 29C 45/1732, B 29C 47/0057, B 29C 2947/92019 |
| 264/40.4 | B 29C 47/92, B 29C 45/76, B 29C 2947/9259, B 29C 2947/92904, B 29C 2947/92647 |
| 264/40.5 | B 29C 45/77, B 29C 45/561, B 29C 45/7653, B 29C 45/76, B 29C 43/58 |
| 264/40.6 | B 29C 45/78, B 29C 47/92, B 29C 2947/92704, B 29C 2947/92209, B 29C 35/0288 |
| 264/40.7 | B 29C 47/92, B 29C 2947/926, B 29C 2947/92904, B 29C 2947/92514, B 29C 2947/92019 |
| 264/41 | C 08J 9/28, B 01D 69/08, D 01D 5/24, B 01D 67/0011, B 01D 69/02 |
| 264/42 | B 28B 1/50, C 04B 38/02, C 04B 28/02, C 04B 2111/00836, A 61F 2/28 |
| 264/43 | C 04B 38/064, C 04B 41/009, B 01D 39/2075, B 28B 1/50, C 04B 38/00 |
| 264/44 | C 04B 38/0615, B 01D 39/2093, C 04B 38/06, C 04B 41/009, C 04B 2111/00793 |
| 264/45.1 | B 29C 44/0461, B 29C 45/1642, B 29K 2105/04, B 29C 44/0492, B 29C 45/00 |
| 264/45.2 | B 29K 2105/04, B 29C 43/12, B 29C 44/1204, B 29C 44/1242, E 04G 11/04 |
| 264/45.3 | B 29K 2105/04, B 29C 44/12, C 08J 9/0066, C 08J 2375/04, B 29K 2075/00 |
| 264/45.4 | B 29C 67/222, B 29K 2105/04, B 29K 2025/00, B |

| | |
|----------|--|
| | 29C 44/445, B 29C 44/12 |
| 264/45.5 | B 29C 44/0407, B 29K 2105/043, B 29C 44/04, B 29K 2105/04, B 29C 67/2235 |
| 264/45.6 | C 08J 7/02, B 29C 44/0461, B 29C 44/5636, B 29C 44/60, B 29C 67/2295 |
| 264/45.7 | B 29C 41/04, B 29K 2105/04, B 29C 41/042, B 29C 41/22, B 29C 44/043 |
| 264/45.8 | B 29C 44/30, B 29C 33/68, B 29C 44/22, B 29C 44/32, B 29L 2009/00 |
| 264/45.9 | B 29C 44/22, B 29C 44/322, B 29C 47/065, B 29K 2105/04, B 29C 67/2235 |
| 264/46.1 | B 29C 44/22, B 29C 67/2235, B 29K 2105/04, B 29C 47/00, B 29C 47/065 |
| 264/46.2 | B 29C 44/30, B 29L 2007/00, B 29L 2009/00, B 32B 27/00, B 29C 44/32 |
| 264/46.3 | B 29C 44/30, B 29C 44/32, B 29C 44/467, B 29L 2007/00, B 29C 44/485 |
| 264/46.4 | B 29K 2105/04, B 29C 44/12, B 29C 44/1271, B 29K 2021/00, B 29K 2075/00 |
| 264/46.5 | B 29C 44/1233, F 25D 23/064, B 29C 44/351, B 29C 44/12, B 29C 44/1257 |
| 264/46.6 | B 29K 2075/00, B 29C 44/14, B 29C 44/143, B 29C 44/18, B 29K 2105/04 |
| 264/46.7 | B 29C 44/12, B 29C 44/1271, B 29K 2075/00, B 29L 2031/751, B 29C 33/0044 |
| 264/46.8 | B 29C 44/146, B 29C 51/10, B 29C 51/082, B 29C 51/16, B 29C 44/14 |
| 264/46.9 | B 29K 2105/04, B 29K 2075/00, B 29C 44/1271, B 29C 53/60, B 29D 99/0032 |
| 264/48 | B 01D 67/0093, B 29C 67/2235, B 29K 2105/043, B 01D 69/02, B 29C 67/2245 |
| 264/49 | C 08J 9/26, B 01D 67/003, B 29C 67/202, C 08J 9/28, B 01D 67/0011 |
| 264/50 | C 08J 9/122, B 29C 44/3446, C 08J 2201/03, C 08J 9/127, B 29C 44/3442 |

| | |
|---------|---|
| 264/51 | B 29K 2105/04, B 29C 67/222, B 29C 67/2235, B 29L 2007/00, B 29L 2023/00 |
| 264/52 | C 08J 9/06, D 06N 7/0013, B 29C 44/10, B 29C 67/2235, C 08J 9/10 |
| 264/53 | B 29C 44/3442, B 29C 67/2235, B 29C 67/222, B 29C 44/3461, C 08J 9/141 |
| 264/54 | B 29K 2075/00, C 08J 9/10, B 29K 2105/04, C 08J 9/06, B 29C 67/2235 |
| 264/55 | C 08J 9/06, C 08J 2327/06, B 29C 45/1642, B 29C 67/221, B 29C 44/0461 |
| 264/600 | C 04B 41/009, C 04B 41/5022, C 04B 35/111, C 04B 35/18, A 47G 21/02 |
| 264/601 | C 04B 33/34, C 04B 41/009, C 04B 41/4505, C 04B 41/81, B 28B 1/54 |
| 264/602 | C 04B 41/009, C 04B 41/52, C 04B 41/89, B 28B 1/005, B 28B 1/26 |
| 264/603 | C 04B 35/565, C 04B 2235/96, C 04B 35/111, C 04B 35/6263, C 04B 2235/5436 |
| 264/604 | C 04B 35/6455, C 04B 35/593, C 04B 35/645, B 22F 3/15, C 04B 2235/3839 |
| 264/605 | B 28B 11/243, C 04B 35/64, B 28B 11/248, C 04B 33/32, C 04B 35/645 |
| 264/606 | F 27B 9/262, C 04B 33/32, F 27B 9/2407, F 27B 9/26, F 27B 9/3011 |
| 264/607 | C 04B 35/64, F 27D 5/00, C 04B 33/32, F 26B 25/18, B 01J 8/1836 |
| 264/608 | C 04B 35/64, C 04B 33/32, C 04B 35/486, C 04B 35/491, B 28B 11/00 |
| 264/609 | F 27B 17/0008, B 28B 11/243, F 27D 3/0022, B 28B 3/126, B 28B 3/20 |
| 264/610 | B 28B 7/342, C 04B 38/065, C 04B 33/28, C 04B 33/30, C 04B 38/0615 |
| 264/611 | C 04B 35/26, C 04B 35/265, C 04B 35/2683, C 04B 35/2625, C 04B 35/2616 |
| 264/612 | C 04B 35/26, C 04B 35/2625, C 04B 35/2658, H |

| | |
|---------|--|
| | 01F 41/16, C 04B 35/265 |
| 264/613 | C 04B 35/2625, C 04B 35/265, C 04B 35/2658, C 04B 35/26, C 04B 35/2683 |
| 264/614 | C 04B 35/111, C 04B 35/634, C 04B 37/001, H 01L 21/4807, H 01L 41/187 |
| 264/615 | C 04B 35/4682, H 01G 4/1227, H 01G 4/30, C 04B 35/47, C 04B 35/49 |
| 264/616 | H 01C 7/112, H 01C 7/043, H 01C 17/30, C 04B 35/111, C 04B 35/4682 |
| 264/617 | H 01C 7/112, C 04B 35/453, H 01C 7/102, H 01C 7/115, C 04B 35/47 |
| 264/618 | Y 02E 60/525, Y 02E 60/521, C 04B 35/113, H 01M 8/1253, H 01M 10/3918 |
| 264/619 | C 04B 41/009, H 05K 1/0306, H 05K 3/4629, B 32B 18/00, C 04B 41/88 |
| 264/620 | C 04B 35/4682, H 01G 4/1227, H 01G 4/2325, B 32B 18/00, C 04B 35/638 |
| 264/621 | C 04B 35/624, C 03B 19/12, C 03C 1/006, C 04B 30/02, C 04B 35/111 |
| 264/622 | C 04B 35/62236, C 04B 35/62231, D 01F 9/08, B 22F 1/004, B 29C 43/22 |
| 264/623 | C 04B 35/62231, C 04B 35/62236, B 28B 11/243, D 01F 9/00, D 01F 9/08 |
| 264/624 | C 04B 35/589, C 04B 35/571, C 04B 35/80, C 04B 35/6316, C 04B 41/009 |
| 264/625 | C 04B 35/571, C 01B 31/36, C 08G 77/60, C 04B 35/589, C 04B 35/806 |
| 264/626 | C 04B 35/589, C 04B 35/581, C 04B 35/591, C 04B 35/5935, C 04B 35/597 |
| 264/627 | D 01F 9/10, C 04B 35/62231, C 04B 35/571, C 04B 35/62236, C 04B 35/62272 |
| 264/628 | C 04B 38/0615, C 04B 2111/00793, C 04B 38/08, C 04B 2111/0081, B 01D 67/0041 |
| 264/629 | F 28F 21/04, B 28B 3/20, B 29C 47/0028, C 04B 38/0003, C 04B 38/0006 |

| | |
|---------|---|
| 264/630 | C 04B 38/0006, C 04B 35/195, C 04B 2111/00793, B 28B 3/269, C 04B 2235/3217 |
| 264/631 | C 04B 35/195, C 04B 38/0006, B 01J 21/14, C 04B 2111/00793, C 04B 2111/0081 |
| 264/632 | C 04B 35/113, C 04B 35/64, B 22F 2998/00, B 28B 1/26, B 28B 11/0854 |
| 264/633 | C 03B 19/06, B 22C 1/165, B 28B 3/00, B 28B 3/003, B 28B 7/00 |
| 264/634 | C 04B 35/634, B 22F 2999/00, B 28B 21/92, C 04B 35/111, C 04B 35/115 |
| 264/635 | B 28B 7/342, B 28B 3/003, C 04B 35/806, B 22C 1/00, B 28B 1/265 |
| 264/636 | B 22F 3/22, B 22F 5/10, B 28B 1/26, B 28B 1/28, B 28B 1/523 |
| 264/637 | B 28B 1/26, B 28B 1/261, B 28B 1/262, C 04B 35/6263, C 04B 2235/5436 |
| 264/638 | C 04B 2235/6021, C 04B 35/632, C 04B 35/634, C 04B 33/00, C 04B 33/32 |
| 264/639 | C 04B 35/62236, C 04B 35/634, C 04B 33/13, D 01F 9/08, C 04B 33/1315 |
| 264/640 | C 04B 35/803, C 04B 35/806, C 04B 35/573, C 04B 35/62868, C 04B 35/6316 |
| 264/641 | C 04B 35/803, C 04B 35/111, C 04B 35/80, C 04B 35/806, C 04B 35/645 |
| 264/642 | C 04B 41/009, C 04B 2235/3826, C 04B 37/001, C 04B 41/87, B 28B 1/008 |
| 264/643 | C 04B 41/009, C 04B 41/87, C 04B 35/593, C 04B 41/52, C 04B 41/89 |
| 264/644 | C 04B 41/009, B 28B 1/008, B 28B 1/16, B 28B 3/24, B 28B 7/183 |
| 264/645 | B 22F 3/225, B 22F 2998/00, C 04B 35/634, C 04B 35/638, B 22F 3/22 |
| 264/646 | C 04B 35/10, C 04B 35/46, C 04B 35/573, C 04B 41/009, B 01J 2/00 |
| 264/647 | C 04B 35/591, C 04B 35/593, C 04B 35/584, C |

| | |
|---------|--|
| | 04B 35/5935, C 04B 35/597 |
| 264/648 | C 04B 35/4682, C 04B 35/4684, C 04B 35/65, H 01G 4/1227, B 22F 1/0059 |
| 264/649 | C 04B 35/651, C 01G 33/00, C 03C 14/004, C 03C 2214/20, C 03C 2214/30 |
| 264/650 | C 04B 35/634, C 04B 35/111, C 04B 35/6342, C 04B 35/63424, C 04B 2235/6025 |
| 264/651 | C 04B 35/565, B 28B 1/26, C 04B 35/10, C 04B 35/51, C 04B 35/573 |
| 264/652 | F 27B 9/262, F 27B 9/3005, F 27B 9/061, F 27B 9/3011, C 04B 33/32 |
| 264/653 | C 04B 35/573, C 30B 31/10, B 01D 39/2037, B 24B 5/18, B 24B 29/04 |
| 264/654 | C 04B 35/64, A 61F 2310/00293, A 61K 6/033, A 61L 27/12, C 01B 25/327 |
| 264/655 | C 04B 35/565, C 04B 35/584, C 04B 35/593, C 04B 35/64, C 04B 41/0072 |
| 264/656 | C 04B 33/13, C 04B 33/1315, C 04B 35/634, C 04B 35/638, B 22F 3/1025 |
| 264/657 | C 04B 35/634, C 08L 53/02, B 22F 1/0059, B 22F 2001/0066, B 22F 3/225 |
| 264/658 | C 01F 5/08, C 04B 35/46, C 04B 35/48, C 04B 35/50, C 04B 35/65 |
| 264/659 | C 04B 35/581, C 04B 35/584, C 04B 35/591, C 04B 35/593, C 01B 21/0685 |
| 264/660 | C 09K 8/80, E 21B 43/267, B 01D 39/06, B 01J 19/30, B 22F 3/002 |
| 264/661 | Y 02E 60/521, Y 02E 60/525, A 61B 19/5223, B 01J 2/26, C 01B 13/14 |
| 264/662 | C 04B 35/64, C 04B 2235/80, C 04B 2235/96, C 04B 35/111, C 04B 35/584 |
| 264/663 | C 04B 35/111, C 04B 35/64, B 01J 3/065, C 01B 21/0825, C 04B 35/03 |
| 264/664 | C 04B 35/575, C 04B 35/593, C 04B 35/6455, C 04B 35/5935, B 02C 17/20 |

| | |
|---------|---|
| 264/665 | C 04B 35/5935, C 04B 41/0072, C 04B 41/009, C 04B 35/584, C 04B 41/80 |
| 264/666 | C 04B 35/5935, C 04B 35/64, C 04B 35/593, C 04B 35/645, B 28B 11/243 |
| 264/667 | C 04B 35/645, C 04B 35/117, C 04B 2235/3201, C 04B 2235/6567, C 04B 2235/77 |
| 264/668 | C 04B 35/584, C 04B 35/597, C 01B 31/36, C 04B 35/58071, C 04B 35/583 |
| 264/669 | C 04B 33/13, C 04B 35/043, C 04B 35/584, C 04B 35/632, C 04B 35/111 |
| 264/670 | C 04B 35/634, C 04B 35/63408, C 04B 35/63416, C 04B 35/63444, B 07B 1/00 |
| 264/671 | C 04B 35/64, C 04B 35/584, C 04B 35/58071, C 04B 35/58078, C 04B 35/5935 |
| 264/672 | B 28B 11/243, C 04B 2235/5445, C 04B 2235/6025, B 32B 18/00, H 01L 21/4857 |
| 264/673 | C 04B 35/64, C 04B 35/584, B 22F 3/10, B 22F 2003/1042, C 04B 35/5935 |
| 264/674 | C 04B 35/565, C 04B 35/581, C 04B 35/64, C 04B 35/575, C 04B 35/01 |
| 264/675 | C 04B 35/14, C 04B 35/565, F 27B 17/0075, A 61K 6/033, A 61L 27/32 |
| 264/676 | C 04B 35/584, C 04B 35/5935, C 04B 35/593, C 04B 35/581, C 04B 35/64 |
| 264/677 | F 27B 9/3005, B 01J 21/063, B 01J 29/06, B 01J 29/40, B 01J 32/00 |
| 264/678 | B 28B 1/00, B 28B 11/14, C 04B 41/009, C 04B 41/91, A 61B 17/2202 |
| 264/679 | B 28B 1/02, B 24D 3/18, B 28B 1/005, B 28B 1/29, B 28B 5/023 |
| 264/680 | B 09B 3/0041, B 28B 1/02, B 28B 1/025, B 28B 7/0064, B 28B 7/0091 |
| 264/681 | C 04B 35/64, C 04B 35/486, C 04B 2235/3217, C 04B 2235/77, C 04B 2235/6562 |
| 264/682 | C 04B 2235/3826, C 04B 35/573, C 04B 35/575, |

| | |
|---------|---|
| | C 04B 2235/422, C 04B 2235/48 |
| 264/683 | C 04B 35/584, C 04B 35/5935, B 32B 21/02, B 32B 27/04, B 32B 27/08 |
| 264/68 | B 29C 65/0672, B 29K 2105/251, B 29C 35/0255, B 29C 47/60, B 29C 57/045 |
| 264/69 | B 29C 45/0082, B 29C 2045/0098, B 29C 45/46, B 44F 9/04, B 29C 45/57 |
| 264/70 | B 28B 1/084, B 28B 3/228, B 28B 5/027, B 29C 47/0026, B 29C 47/54 |
| 264/71 | B 28B 3/022, B 29C 67/244, B 29C 2791/008, B 28B 5/04, B 28B 1/08 |
| 264/72 | B 28B 3/022, B 30B 11/022, B 29C 2791/008, B 28B 7/08, B 27N 5/00 |
| 264/73 | B 44F 9/04, B 29K 2995/0021, B 29C 41/22, B 28B 1/005, B 29C 41/04 |
| 264/74 | B 05D 5/06, B 28B 1/005, B 28B 19/00, B 29K 2021/00, B 44F 9/04 |
| 264/75 | B 29C 47/046, C 11D 13/08, C 11D 13/18, B 29C 47/0021, B 29C 47/0019 |
| 264/76 | D 06N 7/0028, B 29C 43/30, B 29C 43/24, B 29C 43/22, B 29C 70/58 |
| 264/77 | B 29C 43/00, B 29K 2995/0021, B 29C 43/006, B 29C 43/20, B 44F 9/04 |
| 264/78 | D 01F 1/10, D 01F 6/18, D 01F 6/62, D 01F 1/04, D 01F 6/04 |
| 264/79 | C 04B 40/04, C 04B 41/009, E 01C 23/03, B 28B 11/245, C 04B 40/02 |
| 264/80 | B 29C 59/08, B 29C 71/02, B 29C 47/00, B 29K 2021/00, B 29K 2027/12 |
| 264/81 | C 23C 16/01, C 23C 16/22, C 04B 35/522, B 82Y 30/00, C 23C 16/27 |
| 264/82 | C 04B 35/652, B 28B 11/245, C 04B 40/0231, C 04B 28/18, C 04B 28/02 |
| 264/83 | B 27N 3/086, B 29C 49/46, B 29K 2023/06, B 29L 2031/7172, B 29C 2049/4617 |

| | |
|----------------|---|
| 264/84 | B 22F 3/08, B 01J 3/08, B 22F 2998/00, B 29C 44/5627, B 29C 49/06 |
| 264/85 | B 29K 2021/00, D 01D 5/08, B 29K 2077/00, D 01D 1/04, D 01F 6/60 |
| 264/86 | B 28B 1/26, B 28B 1/261, B 28B 7/46, B 28B 1/265, B 28B 7/342 |
| 264/87 | B 28B 7/46, B 28B 1/265, B 28B 1/52, B 28B 1/261, B 28B 3/003 |
| 264/500 | B 29C 45/174, B 29C 2043/566, B 29C 45/1704, B 29C 45/00, B 29C 45/1703 |
| 264/501 | B 29D 30/0602, B 29K 2021/00, B 29D 30/0601, B 29D 23/24, B 29D 30/0661 |
| 264/502 | B 29D 30/0643, B 29C 2035/1658, B 29D 30/36, B 29K 2021/00, B 29D 30/0606 |
| 264/503 | B 29C 47/24, B 29C 47/0026, B 29C 41/04, B 29C 47/0023, B 29C 47/0033 |
| 264/504 | B 26F 1/26, A 61F 13/512, B 29K 2021/00, A 61F 13/15731, B 29C 49/04 |
| 264/505 | B 28B 1/528, B 29C 53/28, B 01J 19/32, B 01J 2219/3221, B 29C 51/10 |
| 264/506 | B 29D 23/18, B 29K 2021/00, B 29C 2049/0089, B 29K 2105/258, B 29C 49/04 |
| 264/507 | B 29K 2021/00, B 29D 23/18, B 29C 53/30, B 29C 49/00, B 29C 49/48 |
| 264/508 | B 29C 47/0033, B 29C 47/0023, B 29C 47/126, B 29C 49/0021, B 29C 2791/006 |
| 264/509 | B 29C 49/2408, B 29C 2049/2412, B 29C 49/04, B 29C 49/24, B 29C 2049/2454 |
| 264/510 | B 29C 70/443, B 29C 43/12, B 29C 70/44, B 29C 70/547, B 29C 70/342 |
| 264/511 | B 29C 2791/006, B 29C 51/10, B 29C 45/1418, B 29C 70/443, B 29C 2045/14286 |
| 264/512 | B 29C 49/22, B 29B 2911/1408, B 29B 2911/14093, B 29B 2911/14053, B 29B 2911/14066 |

| | |
|---------|---|
| 264/513 | B 29B 2911/14093, B 29B 2911/1408, B 29B 2911/14113, B 29C 49/06, B 29C 49/221 |
| 264/514 | B 29C 47/0026, B 29C 47/065, B 29C 47/0023, B 29C 47/0057, B 29C 47/0059 |
| 264/515 | B 29C 49/04, B 29C 49/22, B 29C 49/20, B 29C 47/0023, B 29C 47/065 |
| 264/516 | B 29C 49/20, B 29C 49/04, B 29C 2049/2017, F 16L 55/1651, B 29C 2049/2008 |
| 264/517 | A 61F 13/15626, B 29C 70/305, B 29B 11/16, D 01G 25/00, D 04H 1/70 |
| 264/518 | D 04H 1/72, D 04H 3/16, D 21H 5/2607, B 27N 3/14, A 61F 13/15658 |
| 264/519 | B 29C 47/0026, B 29C 47/0057, B 29C 47/0059, B 29C 47/8835, B 29C 47/86 |
| 264/520 | B 29C 49/06, B 29C 49/04, B 29C 49/6436, B 29B 2911/1402, B 29B 2911/14026 |
| 264/521 | B 29C 49/06, B 29K 2067/00, B 29B 2911/1402, B 29B 2911/14026, B 29B 2911/14033 |
| 264/522 | B 29C 51/10, B 29C 51/04, B 29C 51/06, B 29C 51/422, B 29C 51/426 |
| 264/523 | B 29C 49/06, B 29C 49/04, B 29C 49/48, B 29C 49/4205, B 29C 49/56 |
| 264/524 | B 29C 49/04, B 65B 3/022, B 29L 2031/7158, B 29C 49/06, B 29C 49/46 |
| 264/525 | B 65B 3/022, B 29C 49/04, B 29C 49/46, B 29C 2791/005, B 29C 2049/4635 |
| 264/526 | B 29C 49/04, B 29C 49/06, B 29C 49/60, B 29C 49/48, B 29C 49/4823 |
| 264/527 | B 29C 49/04, B 29C 2049/4869, B 29C 49/4278, B 29C 49/48, B 29C 49/4802 |
| 264/528 | B 29C 49/66, B 29C 2035/165, B 29C 49/12, B 29C 2049/6615, B 29K 2067/00 |
| 264/529 | B 29C 49/04, B 29C 49/18, B 29C 49/06, B 29C 49/12, B 29K 2067/00 |
| 264/530 | B 29C 49/06, B 29C 49/04, B 29C 49/16, B 29C |

| | |
|---------|---|
| | 49/08, B 29C 49/18 |
| 264/531 | B 29C 49/04, B 29L 2031/7158, B 29C 49/06, B 29B 2911/1402, B 29B 2911/14026 |
| 264/532 | B 29C 49/06, B 29C 49/12, B 29B 2911/1402, B 29B 2911/14026, B 29B 2911/14033 |
| 264/533 | B 29C 49/76, B 29C 49/04, B 29L 2031/7158, B 29B 2911/1402, B 29B 2911/14026 |
| 264/534 | B 29C 49/04, B 29C 49/4802, B 29C 49/541, B 29C 2049/4807, B 29C 49/06 |
| 264/535 | B 29C 49/06, B 29C 49/4205, B 29B 2911/1402, B 29B 2911/14026, B 29B 2911/14033 |
| 264/536 | B 29C 49/04, B 29C 49/50, B 29C 49/4817, B 29C 49/4802, B 29C 49/72 |
| 264/537 | B 29C 49/06, B 29B 2911/1402, B 29B 2911/14033, B 29B 2911/1404, B 29B 2911/14026 |
| 264/538 | B 29C 49/06, B 29C 49/36, B 29B 2911/1402, B 29B 2911/14026, B 29B 2911/14033 |
| 264/539 | B 29C 49/022, B 29L 2031/7158, B 29C 47/20, B 29C 47/26, B 29C 47/368 |
| 264/540 | B 29C 49/04, B 29C 49/0005, B 29C 49/48, B 29C 49/041, B 29K 2067/00 |
| 264/541 | B 29C 47/22, B 29C 49/04, B 29C 47/20, B 29C 49/0073, B 29C 47/0023 |
| 264/542 | B 29C 49/04, B 29C 49/32, B 29C 49/42, B 29C 49/56, B 29C 49/421 |
| 264/543 | B 29C 49/04, B 29C 49/36, B 29C 49/70, B 29C 49/32, B 29C 49/56 |
| 264/544 | B 29C 51/10, B 29C 51/002, B 29C 2791/007, B 29C 2791/006, B 29K 2067/00 |
| 264/545 | B 29C 51/267, B 29C 51/10, B 29C 49/0047, B 29C 2791/006, B 29C 51/04 |
| 264/546 | B 29C 43/12, B 29C 51/004, B 29C 51/28, D 06C 23/04, B 29C 31/008 |
| 264/547 | B 29C 51/10, B 29C 51/06, B 29C 51/04, B 29C |

| | |
|---------|--|
| | 51/08, B 29C 2791/006 |
| 264/548 | B 29C 51/10, B 29C 51/32, B 29C 51/34, B 29C 51/445, B 29C 51/00 |
| 264/549 | B 29C 51/04, B 29C 51/10, B 29L 2031/7132, B 29C 57/12, B 29K 2105/04 |
| 264/550 | B 29C 51/04, B 29C 51/10, B 29C 2791/007, B 29C 2791/006, B 29C 51/002 |
| 264/551 | B 29C 51/04, B 29C 51/10, B 29C 51/22, B 29C 51/445, B 26F 1/40 |
| 264/552 | B 29C 51/10, B 29D 99/0057, B 29L 2031/3017, B 29C 2791/006, B 29K 2021/00 |
| 264/553 | B 29C 51/10, B 29C 2791/006, B 29C 51/002, B 29C 51/32, B 29C 51/262 |
| 264/554 | B 29C 51/10, B 29C 2791/006, B 29C 51/04, B 29C 51/08, B 29C 51/082 |
| 264/555 | D 01D 5/0985, D 04H 3/16, D 01D 4/025, D 04H 1/565, D 04H 3/02 |
| 264/556 | B 29C 47/8875, B 29C 47/8845, B 29C 55/00, B 29C 47/0004, B 29C 47/884 |
| 264/557 | B 29C 47/0026, B 29C 47/8835, B 29K 2021/00, A 61F 13/5146, A 61F 13/51476 |
| 264/558 | B 29C 47/0026, B 29C 47/0023, B 29C 47/0057, B 29C 47/902, B 29C 47/0059 |
| 264/559 | B 29C 47/0026, B 29C 47/0059, B 29C 47/0057, B 29C 47/902, B 29C 47/8825 |
| 264/560 | B 29C 47/903, B 29C 47/0026, B 29C 47/0057, B 29C 47/8825, B 29C 47/905 |
| 264/561 | B 29C 47/8895, B 29C 47/0026, A 22C 13/0003, A 22C 13/0013, A 22C 13/0016 |
| 264/562 | B 29C 47/0026, B 29C 47/0057, B 29C 47/0059, B 29C 47/8835, B 29C 47/0023 |
| 264/563 | B 29C 47/0057, B 29C 47/0026, B 29C 47/0059, B 29C 47/0066, B 29C 47/0023 |
| 264/564 | B 29C 47/0026, B 29C 47/0057, B 29C 47/0059, B 29C 47/0004, B 29K 2023/06 |

| | |
|---------|--|
| 264/565 | B 29C 47/0026, B 29C 47/0057, B 29C 47/0059, B 29C 47/902, B 29C 47/0009 |
| 264/566 | B 29C 47/0026, B 29C 47/0057, B 29C 47/0059, B 29C 47/8835, B 29C 47/903 |
| 264/567 | B 29C 47/0026, B 29C 47/0059, B 29C 47/0057, B 29C 47/0009, B 29C 47/903 |
| 264/568 | B 29C 47/903, B 29C 47/0026, B 29C 47/0023, B 29C 47/0059, B 29C 47/0057 |
| 264/569 | B 29C 47/8835, B 29C 47/0026, B 29C 47/0057, B 29C 47/0059, B 29C 47/0009 |
| 264/570 | B 29C 2045/1707, B 29C 43/12, B 29C 45/1704, B 29C 45/1706, B 29C 53/083 |
| 264/571 | B 29C 43/12, B 29C 70/443, B 29C 70/44, B 29C 70/446, B 29C 39/42 |
| 264/572 | B 29C 45/1704, B 29C 45/1711, B 29C 45/1705, B 29C 45/1732, B 29C 45/1734 |
| 264/573 | A 61M 25/1029, A 61L 29/06, B 29C 2049/0089, B 29K 2105/258, B 29L 2023/00 |
| 264/574 | B 29D 22/02, B 29K 2021/00, B 29D 22/04, B 29C 41/14, B 29C 33/30 |
| 264/101 | B 29C 47/76, B 29C 47/762, B 29K 2067/00, D 01D 5/092, B 29C 47/1045 |
| 264/102 | B 29C 47/76, B 29C 70/48, B 29C 39/42, B 29C 37/006, B 29C 45/34 |
| 264/103 | D 01F 6/62, D 01F 8/14, D 02J 1/22, D 01F 6/60, D 01D 5/082 |
| 264/104 | Y 02E 60/12, B 29K 2995/0005, H 01B 1/22, H 01M 4/04, B 29C 70/882 |
| 264/105 | H 01B 1/24, B 29C 70/882, Y 02E 60/50, B 29K 2995/0005, Y 02E 60/12 |
| 264/106 | B 29C 45/263, B 29L 2017/003, B 29L 2017/005, G 11B 3/70, B 29C 45/38 |
| 264/107 | B 29L 2017/003, B 29C 43/02, G 11B 3/70, B 29D 17/005, B 29C 37/02 |
| 264/108 | B 29C 47/0004, B 29K 2105/12, B 29K 2105/06, |

| | |
|---------|--|
| | B 29K 2709/08, B 29C 45/0013 |
| 264/109 | C 08L 97/02, B 22F 2998/00, B 27N 3/00, B 27N 3/002, C 08G 18/6492 |
| 264/110 | H 01B 3/04, C 04B 14/20, C 04B 20/1029, C 04B 26/22, H 01R 43/06 |
| 264/112 | B 27N 5/00, B 29K 2027/18, B 29C 43/18, B 29K 2105/251, B 27N 3/06 |
| 264/113 | B 29C 67/0081, B 29C 43/006, B 27N 3/14, B 29K 2105/251, B 29C 43/203 |
| 264/114 | B 22F 3/06, B 29C 41/20, B 29C 41/365, B 29C 70/326, B 01J 2/14 |
| 264/115 | C 08L 97/02, B 27N 1/00, B 29B 17/0042, B 29C 43/006, B 29B 17/0026 |
| 264/116 | B 27N 3/14, D 04H 1/00, D 04H 1/72, D 21J 1/00, D 21H 5/2635 |
| 264/117 | C 09C 1/58, B 01J 2/00, B 01J 2/12, B 01J 2/28, C 08J 3/12 |
| 264/118 | B 29B 9/06, B 01J 2/20, B 27N 3/183, B 29K 2021/00, B 29K 2311/14 |
| 264/119 | B 27N 5/00, B 29K 2105/251, D 04H 1/70, B 29C 47/0004, D 04H 1/005 |
| 264/120 | B 29K 2105/251, B 27N 5/00, B 29C 43/006, B 29C 43/14, B 29K 2023/0683 |
| 264/121 | D 04H 1/72, B 28B 13/021, B 27N 3/14, D 21H 5/2621, A 61F 13/15658 |
| 264/122 | C 08L 97/02, C 04B 35/645, B 29K 2105/251, D 04H 1/005, B 29C 43/003 |
| 264/123 | D 04H 1/54, B 29K 2311/14, B 29B 15/026, B 29C 43/52, C 04B 30/02 |
| 264/124 | B 27J 5/00, B 27K 7/00, B 27N 1/00, B 27N 3/00, B 27N 3/002 |
| 264/125 | C 04B 35/645, C 04B 33/32, C 04B 35/593, C 04B 33/326, C 01P 2006/10 |
| 264/126 | B 29K 2105/251, B 29C 43/006, C 08J 9/24, B 29C 43/003, B 29C 67/04 |

| | |
|---------|--|
| 264/127 | B 29K 2027/18, B 29C 47/0004, B 29K 2105/251, C 08J 2327/18, B 29C 43/006 |
| 264/128 | D 04H 1/54, C 08L 97/02, B 28B 1/522, B 28B 1/526, B 28B 5/027 |
| 264/129 | C 08J 7/047, C 08J 2321/00, B 29K 2021/00, B 29K 2075/00, B 29K 2105/04 |
| 264/130 | B 29K 2021/00, D 01F 6/62, D 06M 15/53, D 06M 7/00, D 06M 2200/40 |
| 264/131 | B 29K 2021/00, B 29K 2105/251, B 28B 11/06, B 29B 15/105, B 24D 18/00 |
| 264/132 | B 29C 45/14811, B 29C 2045/14237, B 29K 2995/002, B 29C 45/14688, B 29L 2031/722 |
| 264/133 | C 04B 41/009, C 04B 41/52, C 04B 41/70, C 04B 2111/27, B 28B 7/36 |
| 264/134 | C 08J 7/047, B 29C 70/70, B 29D 99/0042, B 29L 2031/54, C 08J 2367/02 |
| 264/135 | B 29C 45/14311, B 29C 39/10, B 29C 70/70, B 29K 2021/00, B 29K 2705/00 |
| 264/136 | B 29B 15/122, B 29C 70/521, B 29K 2105/06, B 29K 2101/12, B 29C 47/027 |
| 264/137 | B 29C 70/525, B 29C 70/521, B 29C 70/50, C 08J 5/24, B 29C 70/46 |
| 264/138 | B 29C 57/00, B 29C 2793/009, B 29K 2021/00, B 29C 43/18, B 29C 45/14409 |
| 264/139 | A 61M 25/0009, B 29C 43/00, B 29D 2030/726, A 61M 25/001, A 61M 25/0012 |
| 264/140 | D 01D 5/40, B 29B 9/04, D 21H 5/202, D 21H 13/14, B 29B 9/06 |
| 264/141 | B 29B 9/06, B 29C 47/0004, B 29C 47/00, C 08J 3/226, B 01J 2/20 |
| 264/142 | B 29B 9/065, B 29B 9/06, B 29C 47/0011, B 29C 47/30, B 29C 2793/009 |
| 264/143 | B 29B 9/06, D 01F 2/06, B 29B 9/065, C 08J 3/12, B 01J 2/20 |
| 264/144 | B 01J 2/24, B 29B 9/04, B 01D 9/0013, B 29C |

| | |
|---------|--|
| | 41/26, C 01C 1/18 |
| 264/145 | B 29C 47/0033, B 29C 47/003, B 29C 47/0066, B 28B 5/028, B 29C 43/222 |
| 264/146 | B 29C 47/0066, B 29C 2793/0063, B 29C 47/0021, B 29C 47/003, B 29K 2021/00 |
| 264/147 | D 01D 5/423, B 29L 2031/731, B 29D 28/00, B 29D 99/0078, B 29K 2021/00 |
| 264/148 | B 29C 47/0066, B 29C 31/048, B 29C 47/00, B 29C 2043/3433, B 29C 43/34 |
| 264/149 | B 29C 47/0023, B 29C 47/0033, B 29C 47/0059, B 29C 47/023, B 29C 47/028 |
| 264/150 | B 29C 47/0023, B 29C 47/0066, B 29K 2021/00, A 61M 25/0009, B 29C 47/0026 |
| 264/151 | B 29C 47/0021, B 29C 47/0066, B 29C 47/00, B 29C 47/0019, B 29C 47/0038 |
| 264/152 | B 29K 2023/06, B 29C 45/006, B 29K 2021/00, B 29K 2023/065, B 29K 2023/12 |
| 264/153 | B 29C 51/32, B 29C 45/14024, B 26F 1/40, B 29K 2021/00, B 29L 2031/565 |
| 264/154 | B 29K 2105/04, C 08J 5/18, B 29D 28/00, B 29K 2021/00, B 26F 1/26 |
| 264/155 | B 28B 1/48, B 29C 33/0033, B 29C 43/00, B 29C 45/00, B 29C 45/14639 |
| 264/156 | B 26F 1/24, B 29C 59/04, B 26F 1/02, B 29C 70/545, A 61F 13/512 |
| 264/157 | B 28B 11/145, B 29K 2021/00, B 28B 11/0818, B 28B 17/0027, B 29C 45/14385 |
| 264/158 | B 26D 3/008, B 29C 2793/009, B 26D 3/16, B 26D 7/01, B 28B 13/0205 |
| 264/159 | B 29K 2021/00, B 29C 31/002, B 29C 2793/00, B 29C 47/0023, B 29C 47/0066 |
| 264/160 | B 29K 2021/00, B 32B 17/10981, B 29C 53/04, B 32B 17/10889, A 61F 2013/15821 |
| 264/161 | B 29C 37/02, B 29C 45/38, B 29K 2021/00, B 29C 43/00, B 29L 2031/26 |

| | |
|------------|---|
| 264/162 | B 28B 11/0818, B 29K 2021/00, B 29C 39/10, B 29C 47/0038, B 29C 33/0033 |
| 264/163 | B 29K 2021/00, B 29C 41/14, B 29C 2793/00, B 26F 1/40, B 29C 37/0057 |
| 264/164 | B 29C 67/00, D 04H 11/08, B 29C 59/025, D 01D 5/08, B 29C 55/00 |
| 264/165 | B 29K 2021/00, B 29C 41/24, B 29C 43/26, B 29C 47/00, B 29D 7/01 |
| 264/166 | B 29K 2021/00, B 29C 43/222, B 29C 47/32, B 29C 47/00, B 29C 47/0023 |
| 264/167 | B 29C 43/222, A 44B 18/0049, B 29L 2031/729, B 29C 47/0033, D 01D 5/20 |
| 264/168 | D 01D 5/22, D 01D 5/23, D 01F 2/06, D 01F 8/08, D 01D 5/30 |
| 264/169 | D 01D 1/106, D 01D 4/022, B 29C 47/68, B 29C 47/12, D 01D 4/02 |
| 264/170 | D 01F 2/10, D 01F 2/08, D 01F 2/06, B 23K 35/40, B 29B 13/06 |
| 264/171.1 | C 08J 5/18, B 29C 47/56, B 32B 27/30, B 29C 47/00, B 29C 47/025 |
| 264/171.11 | B 29C 47/027, B 29C 47/043, B 29C 47/062, B 29C 47/065, B 29C 47/0021 |
| 264/171.12 | B 29C 47/021, B 29C 47/023, B 29C 47/28, B 29D 23/001, B 29K 2021/00 |
| 264/171.13 | B 29C 47/28, B 29B 15/122, B 29C 47/065, B 29C 47/0016, B 29C 47/02 |
| 264/171.14 | B 29C 47/02, B 29C 47/28, B 05D 7/20, H 01B 13/14, B 29C 47/0004 |
| 264/171.15 | B 29K 2021/00, B 29C 35/065, B 29C 47/00, B 29C 47/0004, B 29C 47/02 |
| 264/171.16 | B 29C 47/02, B 29C 47/027, B 29C 47/28, B 29C 47/20, D 07B 7/145 |
| 264/171.17 | B 29C 47/28, B 29L 2031/3462, B 29C 47/128, B 29C 47/0004, B 29C 47/02 |
| 264/171.18 | B 29C 47/128, B 29L 2031/3462, B 29K 2105/20, |

| | |
|------------|--|
| | H 01B 13/14, H 01B 13/24 |
| 264/171.19 | B 29C 47/0004, B 29C 47/02, B 29K 2101/10, B 29K 2301/10, B 29C 47/38 |
| 264/171.2 | B 29C 47/02, B 29C 47/023, B 29C 47/0023, B 29C 47/20, B 29C 47/28 |
| 264/171.21 | B 29C 47/02, B 29C 47/0021, B 29C 47/025, B 29C 47/065, B 29C 70/504 |
| 264/171.22 | B 29C 47/02, B 05D 3/0218, B 05D 3/0272, B 05D 3/08, B 05D 7/20 |
| 264/171.23 | B 29C 47/027, B 29C 47/885, B 05D 1/265, B 29B 15/122, B 29C 43/003 |
| 264/171.24 | B 29K 2021/00, B 29C 47/026, B 29C 70/523, B 29D 99/0078, B 29L 2031/731 |
| 264/171.25 | B 27N 3/206, B 29C 43/003, B 29C 43/06, B 29C 2043/3272, B 29K 2311/14 |
| 264/171.26 | B 29C 47/0023, B 29C 47/065, B 29C 47/26, B 29C 47/0026, B 29C 47/28 |
| 264/171.27 | B 29C 47/0023, B 29C 47/065, B 29C 47/0026, B 29C 47/26, B 29C 47/28 |
| 264/171.28 | A 61L 27/16, A 61L 27/26, B 29C 47/0019, B 29C 47/0023, B 29C 47/06 |
| 264/171.29 | B 29C 47/0023, B 29C 47/065, B 29C 47/0026, B 29C 47/268, B 29C 47/24 |
| 264/172.1 | B 29C 47/0023, B 29C 47/0028, B 29C 47/003, B 29C 47/02, B 29C 47/065 |
| 264/172.11 | D 01D 5/30, D 01D 4/06, D 01D 5/28, D 01F 8/04, A 01D 34/4168 |
| 264/172.12 | D 01D 5/253, D 01F 8/12, D 01D 5/30, D 01D 5/32, D 01F 8/06 |
| 264/172.13 | D 01F 8/14, C 08L 67/02, C 08L 67/04, D 01F 6/92, A 61L 15/225 |
| 264/172.14 | D 01D 5/30, D 01D 5/32, D 01F 8/14, D 01F 8/04, B 29C 47/062 |
| 264/172.15 | D 01D 5/34, B 29C 47/0014, B 29C 47/128, D 01D 5/30, D 01F 8/06 |

| | |
|------------|---|
| 264/172.16 | D 01D 5/32, C 08L 1/02, C 08L 27/06, D 01D 4/02, D 01D 5/06 |
| 264/172.17 | D 01D 5/30, D 01D 5/32, C 08L 67/02, D 01D 5/28, B 29C 47/128 |
| 264/172.18 | C 08G 69/04, C 08G 69/26, D 01F 1/10, D 01F 6/60, A 61F 13/15731 |
| 264/172.19 | A 61K 9/006, A 61K 9/7007, F 26B 13/104, A 61K 9/7015, B 29C 43/22 |
| 264/173.1 | B 29C 47/0019, B 29C 47/065, B 29C 47/0047, B 29C 47/145, B 32B 27/00 |
| 264/173.11 | B 29C 41/32, B 29K 2027/18, B 32B 27/08, A 61B 19/54, A 61B 2017/22038 |
| 264/173.12 | B 29C 47/065, B 29C 47/0019, B 29C 47/145, B 29C 47/56, B 29C 47/0021 |
| 264/173.13 | B 29C 47/065, B 29C 47/0019, B 29C 47/145, B 32B 27/08, B 29C 47/0023 |
| 264/173.14 | B 32B 27/32, B 29C 47/065, B 29C 47/145, B 32B 27/08, B 29C 47/0019 |
| 264/173.15 | B 32B 27/08, B 29C 47/065, B 29C 55/023, B 29C 47/062, B 29C 47/145 |
| 264/173.16 | B 29C 47/065, B 29C 47/0019, B 29C 47/145, B 29C 47/0021, B 29C 47/0023 |
| 264/173.17 | B 29C 47/003, B 29C 47/065, B 29C 47/56, B 60J 10/0005, B 29C 47/0019 |
| 264/173.18 | B 29C 47/065, B 29C 47/0021, B 29C 47/064, B 32B 17/10339, B 29C 47/0019 |
| 264/173.19 | B 29C 47/065, B 29C 47/0021, B 32B 27/32, B 29C 47/0004, B 29C 47/0019 |
| 264/174.1 | B 29C 47/0019, B 29C 47/065, B 29C 47/145, B 29C 47/0816, B 29C 47/16 |
| 264/174.11 | B 29C 47/0004, B 29C 47/065, B 29L 2030/002, A 61F 13/15252, A 61F 13/49009 |
| 264/175 | B 29C 43/24, B 29K 2021/00, B 29C 43/22, B 29C 47/0021, B 29C 47/0038 |
| 264/176.1 | C 08L 67/02, B 29C 47/0004, B 29K 2067/00, C |

| | |
|------------|---|
| | 08J 5/18, B 29C 47/12 |
| 264/177.1 | B 29C 47/003, B 29C 47/14, B 29C 47/0021, B 29C 47/12, C 08J 5/18 |
| 264/177.11 | B 28B 3/269, B 29C 47/0028, B 29C 47/12, B 29L 2031/60, C 03B 17/04 |
| 264/177.12 | B 29C 47/0028, B 29C 47/12, B 29L 2031/60, B 28B 3/269, B 28B 3/26 |
| 264/177.13 | D 01D 5/253, D 01F 6/18, B 29C 47/0014, D 01D 5/04, D 01F 1/10 |
| 264/177.14 | D 01D 5/24, B 29C 47/0023, D 01F 6/18, B 01D 67/0013, B 01D 67/0016 |
| 264/177.15 | B 29C 47/12, B 43K 1/003, B 01D 67/0086, B 01D 69/08, B 29C 47/0009 |
| 264/177.16 | B 29C 47/003, B 29C 47/12, B 29C 47/0021, B 29C 47/0057, B 29C 47/14 |
| 264/177.17 | B 29C 47/003, B 29C 47/14, B 29C 55/065, A 01D 34/4168, A 01D 34/826 |
| 264/177.18 | B 28B 11/243, B 28B 11/246, B 29B 7/56, B 29C 33/04, B 29C 35/06 |
| 264/177.19 | B 29C 47/8815, B 29C 47/003, B 29C 47/0021, B 29K 2995/0072, C 08J 5/18 |
| 264/177.2 | B 29C 47/0004, B 29C 47/003, D 01F 1/10, D 01F 8/14, A 41D 19/01511 |
| 264/178R | B 29C 47/0021, B 29C 47/0057, B 29C 47/0026, B 29C 47/8815, B 29C 47/0023 |
| 264/179 | D 01D 5/06, B 29C 47/8815, D 01F 2/28, D 01F 6/18, B 29C 47/0023 |
| 264/180 | D 01D 5/06, D 01D 5/14, D 01F 2/06, D 01F 6/605, B 29C 47/884 |
| 264/181 | D 01D 5/06, D 01D 5/14, D 01F 2/28, D 02J 1/223, D 01F 2/06 |
| 264/182 | D 01F 6/18, D 01D 5/06, C 08J 2333/20, D 01F 6/54, C 08L 33/20 |
| 264/183 | D 01D 5/06, D 02J 1/227, D 02J 1/226, A 22C 13/0016, B 29B 15/122 |

| | |
|---------|--|
| 264/184 | D 01F 6/605, D 01F 6/72, D 01F 6/74, D 01D 5/06, D 01F 6/60 |
| 264/185 | D 01F 6/14, C 08J 2329/04, B 29K 2029/00, C 08J 5/18, D 01D 5/06 |
| 264/186 | D 01F 9/00, D 01F 9/04, C 08B 1/003, C 08B 37/003, C 08J 2301/02 |
| 264/187 | D 01F 2/00, D 01F 2/28, D 01D 5/06, C 08J 5/18, C 08J 2301/02 |
| 264/188 | D 01F 2/08, D 01F 2/06, D 01D 5/06, D 01F 2/10, D 01F 2/00 |
| 264/189 | D 01F 2/10, D 01F 2/08, D 01F 2/06, C 08B 30/12, D 01F 2/00 |
| 264/190 | D 01F 2/08, D 01F 2/06, C 08B 16/00, D 01F 2/10, A 22C 13/0013 |
| 264/191 | D 01F 2/10, D 01F 2/08, D 01F 2/06, C 08L 1/24, D 01F 1/10 |
| 264/192 | D 01F 2/10, D 01F 2/06, D 01F 2/08, D 01F 2/28, C 22B 1/00 |
| 264/193 | D 01F 2/10, D 01F 2/06, D 01F 2/08, C 08B 16/00, A 22C 13/0013 |
| 264/194 | D 01F 2/10, D 01F 2/06, C 08L 1/24, D 01F 11/02, A 22C 13/0013 |
| 264/195 | D 01F 2/06, D 01F 11/02, D 01F 2/08, D 01F 2/10, D 01D 10/0454 |
| 264/196 | D 01F 2/06, B 29C 47/8895, D 01D 5/06, D 01F 2/08, D 01F 11/02 |
| 264/197 | D 01F 2/06, D 01F 2/08, D 02J 1/223, D 01F 2/10, D 01F 11/02 |
| 264/198 | D 01F 2/06, D 01D 5/06, D 01D 5/12, D 01D 10/0436, D 01F 2/08 |
| 264/199 | D 01F 2/04, D 01D 5/14, D 01D 7/02, B 01F 5/0682, B 29D 7/01 |
| 264/200 | D 01F 2/28, D 01D 5/06, C 08L 1/12, D 01F 2/30, D 01F 2/06 |
| 264/201 | B 29K 2021/00, B 29D 99/0078, B 29L 2031/731, |

| | |
|-----------|--|
| | C 08J 2321/00, C 08J 5/02 |
| 264/202 | D 01F 4/00, A 61L 17/08, C 08L 89/005, A 22C 13/0016, D 01F 6/68 |
| 264/203 | D 01F 6/04, D 01F 6/60, D 01F 6/62, D 01F 2/28, D 01F 6/08 |
| 264/178F | D 01D 5/0885, D 01F 6/60, D 01F 6/62, D 01F 6/18, D 01D 5/088 |
| 264/204 | C 08J 5/18, D 01D 5/04, C 08J 2323/02, D 01F 6/04, B 29C 55/005 |
| 264/205 | D 01D 5/11, D 01D 5/04, D 01F 6/04, D 01F 6/60, D 01F 6/70 |
| 264/206 | D 01F 6/18, D 01D 5/04, D 01F 6/38, C 08J 2333/20, D 01D 4/02 |
| 264/207 | D 01F 2/30, D 01D 5/04, D 01F 2/28, C 08J 5/18, C 08L 1/12 |
| 264/208 | D 01F 2/30, D 01F 2/28, D 01D 1/06, D 01D 5/06, B 29C 47/0021 |
| 264/209.1 | B 29C 47/0023, B 29C 47/0026, B 29C 47/20, B 29C 47/0004, D 01D 5/24 |
| 264/209.2 | B 29C 47/24, B 29C 47/0026, B 29C 47/0023, B 29C 47/20, B 29C 47/0021 |
| 264/209.3 | B 29C 47/0023, B 29C 47/00, B 29C 47/065, B 29C 47/0066, B 29L 2023/22 |
| 264/209.4 | B 29C 47/0023, B 29C 47/0026, B 29C 47/0057, B 29C 47/902, B 29C 47/0038 |
| 264/209.5 | B 29C 47/0057, B 29C 47/0026, B 29C 47/0059, B 29C 47/0023, B 29C 47/902 |
| 264/209.6 | B 29C 47/0004, B 29K 2301/10, B 29C 47/20, B 29K 2101/10, C 08L 23/16 |
| 264/209.7 | B 29C 47/0023, B 29C 47/0026, B 29C 47/20, B 29C 47/28, B 28B 21/52 |
| 264/209.8 | B 29C 47/20, B 29C 47/0023, B 29C 47/28, B 29C 47/0026, B 29K 2105/06 |
| 264/210.1 | C 08J 5/18, B 29C 55/005, B 29C 55/06, B 29C 47/0009, B 29C 47/0014 |

| | |
|------------|---|
| 264/210.2 | B 29C 47/00, B 29C 59/04, B 29C 47/0021, B 29C 47/0038, B 29C 55/18 |
| 264/210.3 | D 01F 6/18, D 01F 6/60, D 01D 5/08, D 01D 5/16, D 01F 6/62 |
| 264/210.4 | D 01F 6/62, D 01F 6/72, D 06M 13/127, A 61L 17/08, A 61L 17/14 |
| 264/210.5 | C 08J 5/18, B 29C 47/0004, B 29C 47/0021, B 29C 47/8845, B 29K 2067/00 |
| 264/210.6 | D 01F 6/04, C 08J 5/18, D 01F 6/62, D 01F 6/60, B 29C 47/0057 |
| 264/210.7 | C 08J 5/18, B 29C 55/143, D 01F 6/62, B 29K 2067/00, D 01F 6/04 |
| 264/210.8 | D 01F 6/62, D 01F 6/04, D 01D 5/16, D 01D 5/08, D 01D 5/12 |
| 264/211 | B 29C 47/0004, D 01F 1/10, B 29C 47/1063, B 29K 2105/0005, C 08K 5/20 |
| 264/211.1 | B 29C 47/52, D 01D 5/18, B 01D 1/222, B 01D 19/0052, B 01J 19/28 |
| 264/211.11 | D 01D 4/02, B 01J 37/0018, B 28B 3/26, C 11D 13/18, B 01J 21/12 |
| 264/211.12 | B 29C 47/0004, D 01F 6/62, D 01F 6/74, B 29C 47/0021, B 29C 47/0023 |
| 264/211.13 | B 29C 47/8815, B 29C 47/0004, B 29K 2067/00, A 61L 31/127, A 61L 31/128 |
| 264/211.14 | D 01D 5/092, D 01D 5/088, D 01D 4/02, D 01D 5/08, D 01F 6/62 |
| 264/211.15 | D 01D 5/08, D 01D 5/092, D 01F 6/62, D 01F 6/60, D 01D 5/084 |
| 264/211.16 | D 01F 6/14, A 61K 9/0073, A 61K 9/1647, A 61K 9/1688, B 29D 99/0078 |
| 264/211.17 | D 01D 5/08, D 01F 6/60, A 47C 5/02, B 05D 5/06, B 05D 7/02 |
| 264/211.18 | C 08J 5/18, C 08J 2367/02, B 29C 35/0261, B 29C 35/045, B 29C 35/06 |
| 264/211.19 | C 08F 6/005, C 08F 8/00, C 08F 255/00 |

| | |
|------------|---|
| 264/211.2 | B 29C 35/025, B 29C 47/00, B 29C 47/0004, B 29K 2021/00, B 29K 2105/06 |
| 264/211.21 | B 29C 47/0004, B 29C 47/60, B 29C 47/38, B 29C 47/80, B 29C 47/92 |
| 264/211.22 | D 01D 1/04, B 29C 47/0014, B 29C 47/80, B 29C 47/38, B 29L 2031/731 |
| 264/211.23 | B 29C 47/50, B 29C 47/38, B 29K 2021/00, B 29K 2105/06, B 29K 2105/16 |
| 264/211.24 | B 29C 47/0004, B 29C 47/40, B 29K 2101/10, B 29K 2301/10, B 01J 19/20 |
| 264/212 | B 29D 7/01, B 29C 41/28, B 29K 2001/00, C 08J 5/18, B 29C 47/8855 |
| 264/213 | B 29C 33/62, B 29C 41/24, B 29C 47/8845, B 29D 7/01, C 09H 9/02 |
| 264/214 | B 29K 2021/00, B 29D 99/0078, B 29L 2031/731, B 29C 43/222, A 44B 18/0049 |
| 264/215 | B 29D 7/01, B 29K 2021/00, B 29K 2105/0064, A 44B 18/0076, B 01D 67/0009 |
| 264/216 | C 08J 5/18, B 29D 7/01, B 29C 41/28, B 29C 47/8845, B 29K 2001/00 |
| 264/217 | B 29D 7/01, B 29K 2001/00, B 29C 41/28, B 29K 2001/12, C 08L 1/08 |
| 264/218 | C 08L 1/00, C 08L 1/08, B 29C 47/8845, B 29D 7/01, B 01D 71/10 |
| 264/219 | B 29C 33/3842, B 29C 33/40, B 29C 33/42, B 29C 33/0033, B 29C 33/306 |
| 264/220 | B 29C 33/3857, B 29C 33/3878, B 29C 33/3842, B 29C 43/021, B 29D 11/00605 |
| 264/221 | B 29C 33/52, B 29C 45/4457, B 29C 33/3857, B 29C 70/446, B 29L 2031/5227 |
| 264/222 | A 61F 2002/5053, A 61F 2/5046, A 61F 2/80, B 29C 2033/3871, H 04R 25/652 |
| 264/223 | A 43B 7/28, A 43D 3/021, B 29C 2033/3871, A 61B 5/1078, A 43D 1/022 |
| 264/224 | B 29D 99/0035, B 29L 2031/324, B 29C 41/14, B |

| | |
|-----------|--|
| | 29C 67/0018, B 29K 2021/00 |
| 264/225 | B 29C 33/3857, B 29C 33/40, B 29C 33/405, B 28B 7/346, B 29C 33/56 |
| 264/226 | B 29C 33/3857, B 29C 33/40, B 29C 33/38, B 29L 2031/757, B 29C 33/56 |
| 264/227 | B 29C 33/40, B 29C 33/3842, B 29C 33/3878, B 29C 33/3885, B 28B 7/346 |
| 264/228 | B 28B 23/04, B 28B 23/043, E 04C 5/08, B 28B 23/06, B 28B 23/046 |
| 264/229 | B 29K 2021/00, A 61F 2/06, A 61F 2/07, A 61F 2002/072, A 61L 27/507 |
| 264/230 | B 29C 61/02, B 29C 71/02, B 29C 63/42, B 29C 61/025, B 29K 2995/0053 |
| 264/231 | B 29K 2021/00, B 29D 29/10, B 29D 29/06, B 29C 35/049, B 29C 35/0277 |
| 264/232 | C 08J 5/18, B 29C 39/00, C 08J 3/18, C 08J 7/00, C 08J 7/047 |
| 264/233 | B 29C 41/14, B 29K 2021/00, D 01F 6/18, B 22F 3/1025, B 28B 7/362 |
| 264/234 | B 29C 71/02, C 04B 28/02, B 01D 63/081, B 01D 63/084, B 22F 1/0059 |
| 264/235 | B 29C 71/02, B 29C 2071/022, C 08J 7/08, B 29C 45/0001, B 29C 2791/001 |
| 264/235.6 | D 02J 1/229, D 01F 6/60, D 01F 6/62, D 02J 1/22, D 01D 5/20 |
| 264/235.8 | B 29K 2067/00, B 29C 55/143, B 29C 71/00, B 29C 55/12, B 29K 2077/00 |
| 264/236 | B 29K 2021/00, B 29C 35/0222, B 29K 2105/243, B 29K 2105/24, B 29L 2031/26 |
| 264/237 | B 29C 45/7207, B 29K 2105/253, B 29C 35/16, B 29C 49/06, B 29B 2911/1402 |
| 264/238 | B 29C 45/006, B 29L 2031/565, B 29C 65/665, B 29C 66/534, A 61F 2/06 |
| 264/239 | B 29K 2021/00, B 30B 15/028, A 23P 1/027, A 47G 23/0216, A 61L 27/16 |

| | |
|---------|--|
| 264/240 | B 29C 67/246, B 29C 37/0032, B 29C 45/1816, A 61L 2/232, B 01D 63/022 |
| 264/241 | B 29C 43/203, B 29C 45/1671, B 29L 2031/3041, B 29C 45/1679, B 29C 69/001 |
| 264/242 | B 29C 45/0017, B 29C 45/14754, B 29C 2045/1601, B 29L 2031/7506, B 29C 45/16 |
| 264/243 | B 29L 2031/425, A 46D 3/005, B 29C 45/14385, B 29L 2031/42, A 46B 2200/1066 |
| 264/244 | B 29K 2021/00, B 29D 35/06, B 29D 35/061, B 29D 35/10, A 43B 1/0027 |
| 264/245 | B 29C 41/22, B 29C 41/18, B 29K 2995/0021, B 29C 39/12, B 44C 3/046 |
| 264/246 | B 29C 45/16, B 29C 41/22, B 29C 45/1635, B 29K 2105/24, B 29K 2995/0021 |
| 264/247 | B 29C 45/16, B 29C 45/14688, B 29C 45/1671, B 29K 2995/0021, B 29L 2031/463 |
| 264/248 | B 29C 65/02, B 29L 2031/545, B 29L 2031/54, B 29C 43/18, B 29K 2021/00 |
| 264/249 | B 29C 66/534, B 29C 66/8322, B 29C 57/00, B 29C 57/025, B 29C 65/606 |
| 264/250 | B 29C 45/16, B 29C 45/1671, B 29L 2031/54, B 29C 2791/001, A 63B 37/0003 |
| 264/251 | B 29C 45/14, B 29C 45/1671, B 29C 45/14336, B 29K 2083/005, B 29K 2713/00 |
| 264/252 | B 29D 5/02, B 29C 47/026, B 60J 10/02, B 29C 70/763, B 29C 45/14573 |
| 264/253 | B 28B 23/028, E 04C 2/288, B 28B 7/342, B 28B 23/02, B 28B 7/0044 |
| 264/254 | B 29C 45/1671, B 29C 70/70, B 29C 45/14, B 29C 2791/001, B 29C 43/18 |
| 264/255 | B 29C 45/16, B 29C 45/1635, B 29C 45/1676, B 29C 37/0028, B 29C 45/1642 |
| 264/256 | C 04B 41/009, B 28B 7/22, B 28B 19/0007, B 28B 21/94, B 28B 7/168 |
| 264/257 | B 29C 70/48, B 29K 2105/06, B 29C 43/12, B 29C |

| | |
|------------|---|
| | 70/443, B 29C 70/44 |
| 264/258 | B 29C 70/46, B 29C 43/12, B 29C 70/443, B 29C 70/342, B 29C 70/345 |
| 264/259 | B 29C 70/78, B 29C 43/18, B 29C 45/14467, B 29C 45/14778, B 29C 45/561 |
| 264/260 | F 16D 2069/002, B 29C 70/28, A 61M 25/09, A 61M 2025/09075, A 61M 2025/09108 |
| 264/261 | B 29C 45/14467, B 32B 17/10917, B 29C 45/14377, B 29C 43/18, B 29C 39/126 |
| 264/262 | B 29C 45/14467, B 29C 45/14491, B 29C 70/74, B 29C 45/1418, B 29C 45/14639 |
| 264/263 | B 29C 45/14467, B 29C 70/72, B 29C 45/14639, B 29C 45/14614, B 29C 65/48 |
| 264/264 | B 29K 2021/00, A 61M 25/1027, B 29C 33/06, B 29C 33/405, B 29C 45/14311 |
| 264/265 | B 28B 21/74, B 29C 41/06, B 29C 41/20, B 29C 41/46, B 29C 43/18 |
| 264/266 | B 29C 45/1418, B 29C 43/184, B 29C 70/78, B 29C 43/18, B 29K 2021/00 |
| 264/267 | B 29C 70/766, B 29L 2023/20, B 29C 45/14598, B 29D 23/20, B 29C 45/14336 |
| 264/268 | B 29C 70/80, B 29C 43/18, B 29L 2031/565, B 29K 2021/00, B 29C 43/00 |
| 264/269 | B 28B 19/0023, B 29C 43/18, B 29C 45/14622, B 29K 2021/00, B 26D 2011/005 |
| 264/270 | B 28B 19/0023, B 05D 7/22, B 05D 1/002, B 05D 7/222, B 28B 21/30 |
| 264/271.1 | B 29K 2001/00, A 61F 2220/0025, A 61F 2/30965, A 61F 2310/00023, A 61F 2310/00029 |
| 264/272.11 | B 29C 45/14639, H 01L 21/565, H 05K 3/284, B 29C 45/14655, B 29C 70/72 |
| 264/272.12 | H 05B 3/30, H 05B 3/46, C 04B 33/28, C 04B 33/30, D 06F 75/24 |
| 264/272.13 | H 01L 21/565, B 29C 45/14655, B 29C 70/72, H 01L 2924/15311, H 01L 21/56 |

| | |
|------------|---|
| 264/272.14 | B 29C 45/14655, H 01L 21/565, B 29C 45/02, B 29C 45/14639, H 01L 2224/48 |
| 264/272.15 | H 01L 21/565, B 29C 45/14655, B 29C 45/14639, B 29C 45/14073, B 29C 33/12 |
| 264/272.16 | B 29C 45/14639, A 61M 11/005, A 61M 15/0085, B 06B 1/0685, B 29K 2709/08 |
| 264/272.17 | H 01L 21/565, B 29C 45/14655, H 01L 21/67126, B 29C 45/02, H 01L 21/566 |
| 264/272.18 | H 01G 13/003, B 29C 33/00, B 29C 33/485, B 29C 43/18, B 29C 45/14 |
| 264/272.19 | H 01F 41/005, H 01F 41/127, B 29C 45/14639, H 02K 15/12, B 29C 39/10 |
| 264/272.2 | H 02K 15/12, B 29C 45/14639, H 01F 41/127, B 29C 39/08, B 29C 39/38 |
| 264/272.21 | Y 02E 60/12, A 46B 5/0062, A 46B 5/007, A 46B 5/02, A 46B 7/04 |
| 264/273 | B 29C 45/14344, B 29C 45/14336, B 29C 45/14, A 61F 2002/30957, B 07B 1/4618 |
| 264/274 | B 29C 33/123, B 29C 43/18, B 29C 37/0082, B 29C 45/14311, B 29C 45/14336 |
| 264/275 | B 29C 45/14065, B 29C 70/70, B 29L 2031/54, B 29C 45/14, B 29C 45/14819 |
| 264/276 | B 29C 45/14639, B 29C 70/72, B 29C 33/0044, B 29C 33/123, B 29C 43/18 |
| 264/277 | B 29C 33/123, B 29C 39/10, B 29C 43/18, B 29C 45/14467, B 29D 35/124 |
| 264/278 | B 29C 45/14073, B 29C 45/14819, B 29L 2031/545, B 29C 33/123, B 29C 41/20 |
| 264/279 | B 29C 45/0025, B 29C 45/14819, B 29C 39/10, B 29C 45/14, B 29C 70/70 |
| 264/279.1 | B 29L 2031/54, A 63B 37/0003, B 29L 2031/545, A 63B 45/00, A 63B 37/0075 |
| 264/280 | B 29C 55/18, B 29K 2021/00, B 29C 35/0277, B 29C 35/049, B 29C 67/0044 |
| 264/281 | B 29D 5/06, B 29C 53/12, A 44B 19/12, B 21D |

| | |
|-----------|---|
| | 53/50, D 02G 1/00 |
| 264/282 | D 02G 1/00, D 02G 1/12, D 06C 21/00, B 31F 1/18, B 31F 1/12 |
| 264/283 | B 31F 1/14, B 31F 1/124, B 29C 55/08, B 29C 55/146, B 29C 55/18 |
| 264/284 | B 29C 59/04, B 31F 1/07, B 31F 2201/0733, B 31F 2201/0738, B 29C 59/046 |
| 264/285 | B 29C 53/04, B 29C 53/083, B 29D 5/04, B 29L 2031/003, D 01D 5/00 |
| 264/286 | B 31F 1/22, B 29C 59/04, B 29K 2021/00, B 28B 1/528, B 29C 53/265 |
| 264/287 | B 29C 55/18, A 24D 3/0204, B 29C 53/265, B 31F 1/122, B 31F 1/22 |
| 264/288.4 | B 29C 55/06, C 08J 5/18, B 29C 55/005, B 29C 55/065, B 29C 55/18 |
| 264/288.8 | B 29C 55/08, B 29C 55/18, D 01D 5/20, D 02J 1/22, D 02J 1/227 |
| 264/289.3 | D 02J 1/221, D 02J 1/228, D 01F 6/60, D 01F 6/62, B 29C 55/00 |
| 264/289.6 | D 01F 6/60, D 01F 6/62, D 02J 1/223, D 02J 1/228, B 29C 55/16 |
| 264/290.2 | B 29K 2067/00, C 08J 5/18, B 29C 55/08, B 29C 55/143, B 29C 55/165 |
| 264/290.5 | D 02J 1/22, D 01F 6/62, D 02J 1/221, D 02J 1/224, D 01D 10/02 |
| 264/290.7 | D 02J 1/225, D 02J 1/224, D 01F 6/60, D 02J 1/228, B 41J 29/46 |
| 264/291 | B 29C 55/00, B 29C 55/005, B 29C 67/00, B 29C 45/0055, B 29C 55/30 |
| 264/292 | B 29C 51/08, B 29C 55/30, B 29C 51/082, B 29C 51/14, B 29C 51/002 |
| 264/293 | B 82Y 10/00, G 03F 7/0002, B 29C 2059/023, B 29C 59/022, B 29C 43/021 |
| 264/294 | B 29C 43/00, B 29K 2021/00, B 28B 13/0205, B 29C 45/561, B 28B 1/02 |

| | |
|-----------|---|
| 264/295 | B 29C 43/00, B 29C 53/083, B 29L 2031/565, B 29C 53/02, B 29K 2021/00 |
| 264/296 | B 29C 57/00, B 29C 57/04, B 29C 57/02, B 29B 13/025, B 29C 45/0055 |
| 264/297.1 | B 29C 43/00, B 22F 3/14, B 28B 3/025, B 29B 13/022, B 29B 17/0026 |
| 264/297.2 | B 29C 45/32, B 29C 45/12, B 29C 45/02, B 29C 45/322, B 29C 45/26 |
| 264/297.3 | B 29C 45/045, B 29C 45/06, B 29K 2067/00, B 29K 2105/253, A 44B 18/0049 |
| 264/297.4 | B 82Y 10/00, G 03F 7/0002, B 29K 2021/00, B 81C 99/0085, B 81C 2201/034 |
| 264/297.5 | B 29D 30/0601, B 29K 2021/00, B 29C 33/0022, B 29C 31/08, B 29C 33/303 |
| 264/297.6 | B 29C 43/08, B 29C 2043/3288, B 29L 2001/00, A 44B 18/0049, A 61J 3/08 |
| 264/297.7 | B 28B 13/0205, B 29C 33/36, B 28B 1/02, B 28B 5/023, B 29C 47/0066 |
| 264/297.8 | B 29C 43/00, A 45D 40/16, B 29D 19/00, A 01K 85/00, A 23G 1/21 |
| 264/297.9 | B 28B 1/02, B 28B 5/023, B 28B 7/0064, B 28B 7/24, B 28B 7/241 |
| 264/298 | B 01D 69/122, B 05D 1/202, B 29C 39/38, B 29D 7/01, B 82Y 30/00 |
| 264/299 | B 30B 11/205, B 29C 33/0033, B 29C 33/04, B 29C 2791/006, B 29L 2031/26 |
| 264/300 | B 29C 33/60, B 29C 33/64, C 08G 2120/00, C 08G 2125/00, C 08K 5/098 |
| 264/301 | B 29C 41/14, C 08J 5/02, B 29K 2021/00, C 08J 2321/00, B 29C 41/18 |
| 264/302 | B 29C 41/18, B 29C 41/46, B 29C 41/22, B 29K 2105/251, B 29K 2995/0021 |
| 264/303 | B 29C 41/14, B 29K 2021/00, B 29L 2031/4864, B 29D 99/0067, A 41D 19/0062 |
| 264/304 | B 29C 41/14, B 29K 2021/00, C 08J 2321/00, B |

| | |
|---------|---|
| | 29K 2001/00, C 08J 5/02 |
| 264/305 | C 08J 5/02, C 08J 2321/00, A 63B 37/0023, B 29C 71/02, C 08G 18/0852 |
| 264/306 | C 08J 2321/00, C 08J 5/02, B 29C 41/14, B 29K 2021/00, B 29L 2031/4864 |
| 264/307 | B 29C 41/14, B 29C 71/0009, B 29D 99/0096, B 29K 2021/00, B 29K 2105/0064 |
| 264/308 | B 29C 67/0092, B 29C 41/36, B 29C 67/0055, B 29C 67/0059, B 29C 41/52 |
| 264/309 | B 29C 41/08, B 28B 13/02, B 29K 2021/00, B 29K 2105/12, B 29L 2031/3008 |
| 264/310 | B 29C 41/04, B 29C 41/06, B 29C 41/003, B 29C 41/46, B 29K 2105/251 |
| 264/311 | B 29C 41/04, B 29C 39/08, B 29C 41/06, B 29C 41/042, B 29C 41/045 |
| 264/312 | B 28B 1/02, B 28B 21/245, B 29C 45/5605, B 28B 21/24, B 29C 67/0003 |
| 264/313 | B 29C 33/505, B 29C 33/405, B 29K 2021/00, B 29L 2023/22, B 29C 33/76 |
| 264/314 | B 29C 43/12, B 29C 43/3642, B 29C 70/446, B 29C 70/342, B 28B 3/003 |
| 264/315 | B 29D 30/0601, B 29D 30/0645, B 29L 2030/00, B 29D 30/0654, B 29D 2030/0655 |
| 264/316 | B 29K 2021/00, B 29C 33/68, B 29C 43/12, B 29C 53/04, B 29C 33/00 |
| 264/317 | B 29C 33/52, B 29C 33/448, B 28B 7/342, B 29D 30/02, B 29D 30/0606 |
| 264/318 | B 29C 45/4407, B 29D 1/00, B 29L 2031/565, B 29C 45/33, B 29C 45/2618 |
| 264/319 | G 03F 7/0002, B 82Y 10/00, B 29C 59/022, B 29C 43/00, B 29C 43/003 |
| 264/320 | B 29C 43/021, B 29C 59/02, B 29K 2021/00, B 29C 43/36, B 29L 2031/712 |
| 264/321 | B 29C 44/5636, B 29K 2105/04, C 08J 9/36, B 29C 44/5627, C 08J 2375/04 |

| | |
|------------|--|
| 264/322 | B 29C 51/082, B 29C 43/52, B 29C 57/00, B 29C 53/04, B 29C 43/16 |
| 264/323 | B 29C 55/30, B 29C 47/0004, B 29C 47/54, B 29C 47/86, B 29C 33/20 |
| 264/324 | B 29K 2021/00, B 29C 33/00, B 29D 99/006, B 29K 2105/06, B 29K 2105/25 |
| 264/325 | B 29K 2021/00, B 29C 43/00, C 04B 35/593, B 29C 43/021, B 29C 43/02 |
| 264/326 | B 29D 30/0629, B 29D 30/0606, B 29D 30/0601, B 29K 2021/00, B 29L 2030/00 |
| 264/327 | B 29C 45/73, B 29C 33/00, B 29C 39/006, B 29C 39/38, B 29K 2063/00 |
| 264/328.1 | B 29C 45/0001, B 29C 45/26, B 29C 45/40, B 29C 45/2628, B 29C 45/00 |
| 264/328.2 | B 29K 2021/00, B 29K 2101/10, B 29C 45/0001, B 29K 2083/005, B 29C 45/2701 |
| 264/328.3 | B 29C 45/2616, B 29C 45/2606, B 29C 45/2628, B 29C 45/2701, B 29C 45/36 |
| 264/328.4 | B 29C 45/72, B 29C 45/00, B 29C 45/02, B 28B 1/24, B 29C 45/54 |
| 264/328.5 | B 29C 45/02, B 29C 45/462, B 29C 45/00, B 29C 45/463, B 29K 2105/255 |
| 264/328.6 | B 29C 67/246, C 08G 2120/00, B 29C 45/0001, C 08G 18/10, C 08G 18/08 |
| 264/328.7 | B 29C 45/561, B 29C 2045/563, B 29C 45/56, B 29C 2045/564, B 29C 2045/5695 |
| 264/328.8 | B 29C 45/26, B 29C 45/0025, B 29C 45/16, B 29C 45/0046, B 29C 45/2725 |
| 264/328.9 | B 29C 45/0025, B 29C 45/2806, B 29C 45/28, B 29C 45/281, B 29C 45/30 |
| 264/328.11 | B 29C 45/07, B 29C 45/2708, B 29C 45/33, B 29C 45/40, B 29C 45/561 |
| 264/328.12 | B 29C 45/0025, B 29C 45/0046, B 29C 45/36, B 29C 45/26, B 29C 45/2708 |
| 264/328.13 | B 29C 45/00, B 29C 45/82, A 61B 17/7004, A 61B |

| | |
|------------|--|
| | 17/701, A 61B 17/7011 |
| 264/328.14 | B 29C 45/0001, B 29C 45/00, B 29C 35/16, B 29C 45/2725, B 29C 45/46 |
| 264/328.15 | B 29C 45/2737, B 29C 45/30, B 29C 45/00, B 29C 45/72, B 29C 45/60 |
| 264/328.16 | B 29C 45/0001, B 29C 45/73, C 08L 67/02, B 29C 45/00, B 29C 45/46 |
| 264/328.17 | B 29C 45/0001, B 29C 45/60, B 29C 45/47, B 29C 45/52, B 29C 45/0013 |
| 264/328.18 | B 29C 45/0005, B 29C 45/0013, B 29C 45/0001, B 29C 45/60, B 29C 47/1045 |
| 264/328.19 | B 29C 45/54, B 29C 45/2806, B 29C 45/531, B 29C 2045/1792, B 29C 2045/2813 |
| 264/330 | B 29C 67/241, C 08L 95/00, B 29C 39/06, B 29C 39/38, C 10G 73/40 |
| 264/331.11 | C 08L 101/00, A 45D 31/00, A 61K 8/0229, A 61K 8/26, A 61L 27/16 |
| 264/331.12 | B 29C 39/006, C 08L 63/00, A 61F 2/3094, A 61F 2/34, A 61L 27/16 |
| 264/331.13 | B 29K 2021/00, A 01N 43/50, A 01N 43/653, A 41D 19/0058, A 41D 19/0096 |
| 264/331.14 | B 29C 43/003, B 29K 2027/12, B 29K 2027/16, B 01D 69/12, B 01D 2323/26 |
| 264/331.15 | C 08J 5/00, B 29C 43/003, B 29K 2027/06, B 29K 2105/251, C 08J 2327/06 |
| 264/331.16 | C 08F 20/42, C 08F 20/44, C 08J 3/00, C 08J 2333/18, C 08L 67/06 |
| 264/331.17 | B 03B 9/06, B 03B 9/061, B 09B 3/0033, B 29B 17/02, B 29B 2017/0203 |
| 264/331.18 | A 61F 2/30723, A 61F 2/3094, A 61F 2002/30062, A 61F 2002/30881, A 61F 2210/0004 |
| 264/331.19 | B 29C 33/60, B 29C 33/62, B 29C 39/006, B 29K 2075/00, B 29K 2077/00 |
| 264/331.21 | B 27N 3/002, B 27N 5/00, B 29B 13/02, B 29B 13/06, B 29C 43/003 |

| | |
|------------|--|
| 264/331.22 | B 01J 20/28026, B 01J 20/28042, B 29C 39/006, F 16D 69/021, F 16D 69/022 |
| 264/332 | C 04B 35/645, B 28B 1/54, C 04B 35/563, C 04B 35/58071, C 04B 35/5611 |
| 264/333 | C 04B 28/02, C 04B 28/04, C 04B 28/14, B 28B 7/0097, B 28B 7/18 |
| 264/334 | B 29C 37/0003, B 29D 30/0603, B 29D 30/0649, B 29C 45/40, B 29C 45/4225 |
| 264/335 | B 29C 37/0017, B 29C 33/46, B 29C 45/43, B 29D 30/0649, B 29K 2021/00 |
| 264/336 | B 28B 5/08, B 28B 7/168, B 28B 7/241, B 29C 45/7207, B 29K 2105/253 |
| 264/337 | B 29C 33/38, B 29C 33/405, B 29K 2033/04, A 21B 3/131, A 21B 3/132 |
| 264/338 | B 29C 33/60, B 29C 33/56, B 29C 33/64, B 29C 33/62, B 29K 2021/00 |
| 264/339 | B 29C 53/04, B 29C 53/083, B 29C 67/00, B 29C 53/043, B 29C 57/12 |
| 264/340 | C 08J 7/02, D 06M 13/358, C 08L 89/00, D 06M 2101/06, A 61F 13/4902 |
| 264/341 | C 08J 7/02, B 29C 71/0009, B 29C 37/02, C 08J 2301/14, B 29K 2069/00 |
| 264/342R | B 29C 71/02, B 29K 2021/00, A 61M 25/0012, A 61M 25/0045, A 61M 25/005 |
| 264/342RE | B 29C 51/002, B 29C 53/18, B 29C 59/00, B 29C 59/04, B 29C 61/00 |
| 264/343 | C 08J 7/02, C 08J 2369/00, B 29C 65/4895, C 08L 1/00, A 01C 1/06 |
| 264/344 | C 04B 35/632, C 04B 35/638, D 01F 6/74, B 22F 3/1025, C 08L 1/00 |
| 264/345 | B 29C 71/02, Y 02E 60/126, H 01M 4/21, B 29K 2067/00, B 29C 2071/022 |
| 264/346 | B 29C 71/02, C 08J 7/08, B 29C 35/16, B 29C 67/00, B 29C 2035/0822 |
| 264/347 | B 29K 2021/00, B 29C 47/00, B 29C 35/065, B |

| | |
|---------|---|
| | 29C 35/049, B 29C 35/0277 |
| 264/348 | B 29C 45/7207, B 29C 49/06, B 29C 2035/1658, B 29B 2911/14593, B 29C 35/16 |
| 264/349 | B 29C 47/38, B 29C 47/0004, B 29C 47/60, B 29B 7/125, B 29C 47/1063 |
| 264/900 | B 29K 2067/00, B 29C 71/02, B 29C 49/06, B 29C 49/08, B 29C 49/6472 |
| 264/901 | B 29K 2067/00, B 29C 51/426, B 29C 51/002, B 29C 51/04, B 29K 2023/12 |
| 264/902 | B 29C 55/28, B 29C 47/0026, B 29C 47/0057, B 29C 47/0059, B 29C 55/26 |
| 264/903 | B 29K 2067/00, B 29C 49/06, B 29K 2995/004, B 29K 2995/0041, B 29C 49/64 |
| 264/904 | B 29K 2067/00, B 29C 49/06, B 29C 49/12, B 29K 2995/0017, B 29C 49/6472 |
| 264/905 | B 29C 49/06, B 29K 2067/00, B 29C 49/6481, B 29K 2995/0017, B 29C 49/18 |
| 264/906 | B 29C 49/06, B 29C 49/649, B 29K 2067/00, B 29C 61/02, B 29K 2995/0017 |
| 264/907 | B 29K 2067/00, B 29C 49/06, B 29B 2911/1402, B 29B 2911/14026, B 29B 2911/14033 |
| 264/908 | B 29K 2067/00, B 29C 49/06, B 29K 2995/0041, B 29K 2995/004, B 29B 2911/1402 |
| 264/909 | B 29C 49/00, B 29C 61/02, B 29K 2995/0053, B 29K 2067/00, B 29C 51/06 |
| 264/910 | C 04B 35/115, C 04B 35/505, C 04B 35/645, C 04B 35/6455, G 01T 1/2023 |
| 264/911 | B 29K 2105/26, B 29B 17/0042, B 29B 17/02, B 29B 17/0026, C 08J 11/06 |
| 264/912 | B 29K 2021/00, B 29L 2030/00, B 29B 17/0042, B 29K 2105/26, C 08J 2321/00 |
| 264/913 | B 29K 2105/06, B 29B 17/02, B 29B 17/0042, B 29K 2105/26, B 29L 2031/7322 |
| 264/914 | B 27N 3/007, B 29B 17/0026, B 29B 17/0042, B 29B 17/02, B 29K 2105/26 |

| | |
|-----------|---|
| 264/915 | B 29B 17/02, B 29K 2105/26, B 29B 17/0042, B 29K 2105/06, B 29K 2705/00 |
| 264/916 | B 29K 2105/04, B 29K 2025/00, B 29B 17/0026, B 29K 2075/00, B 29B 17/0042 |
| 264/917 | B 29K 2067/00, B 29K 2105/26, B 29B 2911/1408, B 29B 2911/14093, B 29B 2911/14053 |
| 264/918 | B 29K 2067/00, B 29B 17/02, B 29L 2031/7158, B 29B 17/0042, B 29K 2023/06 |
| 264/919 | B 27N 3/007, B 27N 5/00, B 29B 13/10, B 29B 17/0036, B 29B 17/0042 |
| 264/920 | B 29B 17/0042, B 29K 2105/26, B 29B 17/02, B 29B 17/0026, B 29C 47/0004 |
| 264/921 | B 29K 2105/26, B 29B 17/0042, B 29K 2105/12, B 29B 17/0412, B 29K 2067/00 |
| 264/DIG1 | B 29K 2105/04, B 29C 49/04, B 29C 49/22, B 29C 44/146, B 29C 49/0005 |
| 264/DIG2 | C 08J 2361/06, C 08J 2361/00, B 29C 44/00, C 08J 9/06, C 08J 2361/24 |
| 264/DIG3 | C 08J 2327/06, B 29C 67/2295, C 08J 9/08, B 29C 67/2235, C 08J 9/0061 |
| 264/DIG4 | B 29C 44/5627, C 08J 9/36, B 29K 2025/00, C 08J 9/04, B 29C 37/0057 |
| 264/DIG5 | C 08J 9/0061, C 08J 9/149, C 08J 2323/02, B 29C 67/2235, B 29C 44/3442 |
| 264/DIG6 | C 08J 9/32, B 29C 70/66, B 29K 2105/165, B 29K 2105/16, B 29C 70/025 |
| 264/DIG7 | B 29C 67/207, C 08J 9/35, B 29K 2105/04, C 08J 2375/04, B 29C 67/221 |
| 264/DIG8 | D 01D 5/423, D 04H 13/00, D 01D 5/247, B 03C 3/28, B 29C 67/2235 |
| 264/DIG9 | B 29C 44/3461, C 08J 9/228, B 29C 67/222, C 08J 9/18, C 08J 2325/06 |
| 264/DIG10 | B 29C 67/222, B 29C 44/445, B 29L 2031/7132, B 29C 44/206, B 29C 44/3461 |

| | |
|-----------|--|
| 264/DIG11 | B 29C 67/222, B 29C 33/0033, B 29C 44/583, B 29C 44/343, B 28B 7/42 |
| 264/DIG12 | B 28B 5/025, B 29C 44/206, B 28B 5/04, B 29L 2007/00, B 27J 5/00 |
| 264/DIG13 | B 29C 67/2235, C 08J 9/0061, C 08J 2327/06, B 29K 2105/04, C 08J 9/12 |
| 264/DIG14 | B 29K 2105/043, C 08J 9/34, C 08J 2375/04, B 29C 67/2235, B 29K 2105/04 |
| 264/DIG15 | B 29C 67/222, C 08J 9/228, B 29C 44/3461, C 08J 9/232, B 29C 44/5609 |
| 264/DIG16 | C 08J 2323/10, C 08J 2323/02, C 08J 9/0061, B 29C 67/2235, B 29K 2023/12 |
| 264/DIG17 | C 08J 9/0066, C 08J 2375/04, C 08J 9/00, C 08J 9/0061, B 29C 67/2235 |
| 264/DIG18 | C 08J 2323/02, C 08J 9/0061, C 08J 9/10, B 29K 2105/24, C 08J 9/06 |
| 264/DIG19 | C 01P 2004/10, C 04B 35/62231, C 03C 13/00, D 01F 9/22, C 04B 35/62236 |
| 264/DIG20 | C 04B 35/03, C 04B 35/013, C 21C 5/44, C 04B 35/532, C 04B 41/85 |
| 264/DIG25 | C 04B 35/46, C 04B 33/02, B 65H 57/24, B 65H 2701/31, C 04B 35/01 |
| 264/DIG26 | D 01D 5/30, D 01D 5/32, D 01D 5/34, D 01F 8/12, D 02G 1/18 |
| 264/DIG27 | D 01F 2/06, D 01F 2/08, D 01F 2/10, D 01D 5/06, A 61K 33/18 |
| 264/DIG28 | D 01D 10/0481, B 65H 2701/31, B 65H 51/16, D 01D 5/08, D 02J 1/222 |
| 264/DIG29 | C 03B 37/045, C 03B 37/0753, C 03C 2213/04, C 08L 23/10, C 08L 2023/42 |
| 264/DIG30 | A 61F 2002/5053, A 61F 2/5046, A 43B 7/28, A 61F 2/80, A 43D 1/022 |
| 264/DIG31 | B 44F 9/08, B 28B 1/008, B 28B 7/0073, B 44F 9/04, C 04B 41/009 |
| 264/DIG32 | C 08L 95/00, B 28B 1/52, C 10C 3/14, C 04B |

| | |
|-----------|---|
| | 28/02, C 04B 41/009 |
| 264/DIG33 | B 29C 47/22, B 29C 49/04, B 29C 49/0073, B 29C 47/0023, B 29C 49/06 |
| 264/DIG34 | B 29C 43/00, B 29D 19/00, B 29L 2019/00, B 29D 19/04, B 29C 33/0033 |
| 264/DIG35 | B 22F 3/15, B 30B 11/007, C 04B 18/027, C 04B 28/186, C 04B 28/34 |
| 264/DIG36 | C 04B 35/565, C 04B 35/645, C 04B 35/52, C 04B 41/009, C 22C 32/00 |
| 264/DIG37 | A 61J 3/07, A 61J 3/077, B 29C 41/14, B 29C 51/225, A 61K 9/4816 |
| 264/DIG38 | C 08L 89/005, C 08L 89/00, B 29C 43/00, B 29D 19/00, C 08L 89/06 |
| 264/DIG39 | C 04B 33/30, C 04B 33/28, C 04B 33/02, C 04B 20/068, C 04B 33/06 |
| 264/DIG40 | B 29C 53/12, H 01B 13/008, B 21F 3/04, B 29D 5/06, B 29C 47/0035 |
| 264/DIG41 | B 29L 2023/20, B 29D 23/20, B 29C 45/14598, B 65D 35/12, B 29L 2001/00 |
| 264/DIG42 | B 22C 9/126, B 29C 47/0004, B 29C 47/8805, B 29K 2021/00, B 29K 2101/10 |
| 264/DIG43 | B 28B 11/245, C 04B 28/02, C 04B 40/04, C 04B 28/04, C 04B 41/009 |
| 264/DIG44 | B 29C 33/52, B 28B 7/342, B 29C 33/448, B 29C 45/4457, B 22C 7/02 |
| 264/DIG45 | B 21D 26/14, B 29K 2101/10, B 05B 5/14, B 29C 41/08, B 29C 41/14 |
| 264/DIG46 | B 29C 35/12, B 29K 2021/00, B 29L 2030/00, B 29C 65/04, B 29C 35/08 |
| 264/DIG47 | D 01D 5/423, B 29D 28/00, D 04H 13/00, D 01D 5/42, B 29C 47/0021 |
| 264/DIG48 | B 01D 46/0001, B 01D 29/111, B 29L 2031/14, B 01D 46/10, B 01D 46/521 |
| 264/DIG49 | C 04B 28/021, C 04B 28/02, C 04B 18/021, C 04B 28/04, C 04B 18/027 |

| | |
|-----------|---|
| 264/DIG50 | B 29K 2021/00, B 29C 43/12, B 29C 51/10, B 30B 11/001, B 27D 1/083 |
| 264/DIG51 | B 01J 2/16, D 06B 19/0082, B 01J 2/02, B 01J 8/36, B 29K 2105/251 |
| 264/DIG52 | B 29K 2021/00, B 29D 23/18, B 29L 2023/18, B 29L 2031/4835, B 29D 99/0071 |
| 264/DIG53 | B 29C 70/326, B 29C 43/12, B 29K 2105/06, B 32B 27/00, B 29K 2309/08 |
| 264/DIG54 | H 01B 19/00, B 28B 1/002, B 29L 2031/3412, B 28B 11/00, H 01B 17/20 |
| 264/DIG55 | A 44C 27/00, A 44C 17/04, B 24B 1/00, B 24B 9/16, B 29C 33/306 |
| 264/DIG56 | B 29K 2077/00, C 08G 69/18, C 08G 69/16, D 06M 13/127, D 01F 6/60 |
| 264/DIG57 | B 28B 1/16, C 04B 41/009, B 28B 1/008, B 28B 7/0088, B 28B 19/00 |
| 264/DIG58 | C 04B 35/2683, H 01F 41/0273, C 04B 35/26, H 01F 41/0246, H 01F 1/26 |
| 264/DIG59 | B 29K 2105/243, B 29C 2791/001, B 29K 2105/24, B 29C 43/021, B 29C 43/14 |
| 264/DIG60 | B 29C 41/18, B 29C 41/22, C 08J 2327/06, B 29C 41/46, B 29K 2027/06 |
| 264/DIG61 | B 29K 2077/00, D 01F 6/60, H 01M 2/1653, Y 02E 60/12, C 08J 9/24 |
| 264/DIG62 | B 29C 67/202, C 08J 9/28, B 01D 69/10, B 01D 71/56, B 01D 69/02 |
| 264/DIG63 | C 04B 38/02, C 04B 2111/52, C 04B 28/02, C 04B 38/00, C 04B 38/064 |
| 264/DIG64 | B 29C 43/00, C 08J 9/06, B 29C 31/066, B 29B 2911/1402, B 29B 2911/14026 |
| 264/DIG65 | B 29C 43/00, B 29B 13/02, B 29C 33/02, B 29C 43/52, B 29K 2105/251 |
| 264/DIG66 | B 29C 57/00, B 29C 43/00, B 29K 2021/00, B 29C 67/00, B 29C 53/04 |
| 264/DIG67 | B 29L 2031/26, B 29K 2021/00, B 29D 99/0053, B |

| | |
|-----------|---|
| | 29C 43/18, F 16J 15/328 |
| 264/DIG68 | B 29C 55/18, B 29L 2031/324, B 29C 43/24, B 29C 47/0038, B 29C 59/04 |
| 264/DIG70 | B 29C 47/0033, B 29K 2021/00, B 29L 2028/00, B 26F 1/24, B 26F 1/26 |
| 264/DIG71 | B 29C 61/02, B 29C 61/025, B 29K 2105/04, B 29C 61/003, B 29K 2995/0049 |
| 264/DIG72 | B 29C 41/08, B 29K 2021/00, B 29C 41/04, B 29K 2105/0064, B 21D 37/20 |
| 264/DIG73 | B 29C 47/0057, B 29C 55/06, B 29C 55/165, B 29K 2021/00, C 08J 5/18 |
| 264/DIG74 | B 29D 30/54, B 29L 2030/00, B 29C 73/10, B 29C 73/02, B 29C 73/06 |
| 264/DIG75 | D 04H 3/16, D 04H 1/54, D 01D 5/0985, D 04H 1/565, D 01D 5/04 |
| 264/DIG76 | B 29C 66/534, B 29C 65/02, B 29C 43/18, B 29C 65/18, B 29C 66/54 |
| 264/DIG77 | C 08G 18/10, D 01F 6/72, B 29K 2075/00, C 08L 75/00, D 06N 3/14 |
| 264/DIG78 | B 29C 43/12, B 28B 7/44, B 29C 39/42, B 29C 51/10, B 29C 2791/006 |
| 264/DIG79 | B 29C 41/18, B 29C 41/22, B 26F 3/08, B 27N 3/00, B 29C 33/0038 |
| 264/DIG80 | C 04B 41/009, C 04B 41/52, C 04B 2111/27, A 61B 5/031, A 61B 5/076 |
| 264/DIG81 | B 29L 2028/00, B 29C 47/0033, B 29C 47/12, B 29D 28/00, B 29C 47/122 |
| 264/DIG82 | D 06N 7/0013, C 08J 9/101, B 44C 1/205, D 06N 3/06, B 32B 5/20 |
| 264/DIG83 | B 29C 45/00, C 08G 2120/00, B 29C 44/0492, B 29C 44/3442, B 29C 67/246 |
| 264/DIG84 | B 29C 44/28, B 29C 44/467, B 29C 44/462, B 29C 67/226, B 29L 2007/00 |

Most statistically relevant CPC Subclasses

G 21C, B 29C, G 02B, C 04B, C 03B, G 03H, B 29D, C 06B, A 61K, B 01J, B 01F, D 04H, D 01D, A 61C, C 09K, B 23K, H 01M, C 08J, B 01D, B 28B, H 01F, H 01L, B 29K, A 61F, D 01F, F 27D, E 04G, E 04B, G 11B, C 10M, F 27B, C 23C, B 29B, B 27J, H 01B, B 05D, C 08G, B 32B, C 08F, B 29L, C 08L, D 02J, H 05B, A 61M, H 02K, D 02G, D 06M, A 61J, D 06N