

- | | | | |
|-------|--|-------|--|
| 1 | MISCELLANEOUS | 20 | .Disk cutting |
| 2 | DRESSING | 21 | .Endless |
| 3 | .Rotary cutter | 22 | .Saw teeth |
| 4 | ..Cutter-support feed | 23.01 | SPLITTING, SHEARING, AND PUNCHING |
| 5 | ..Rotary tools | 23.02 | .Roller-type cutter |
| 6 | .Pick-action cutter | 24 | .Mica splitting |
| 7 | ..Cutter-support feed | 25 | SLATE SURFACING |
| 8 | .Arm-supported tool | 26 | BRICK CLEANING |
| 9 | PLANING | 27 | MILLSTONE DRESSING |
| 10 | TURNING | 28 | .Rotary cutter |
| 11.01 | .Grinding-wheel dressing | 29 | .Pick-action cutter |
| 11.02 | ..Indexing of tool point | 30.01 | PRECIOUS STONE WORKING |
| 11.03 | ..Rotary or crush dressing | 30.02 | .Wire drawing die making |
| 11.04 | ..Contouring of grinding wheel
face | 35 | WORK SUPPORTS |
| 11.05 | ...Cam controlled | 36 | TOOLS |
| 11.06 | ...Templet- or pattern-controlled | 37 | .Traction rotated |
| 11.07 | ...Hydraulically actuated | 38 | .Surface traversing |
| 11.08 | ...Pantograph | 39 | ..Diamond |
| 11.09 | ...Fulcrum bar | 40 | .Impact |
| 11.1 | ...Tangent bar forms arcuate
surface | 41 | ..Bush hammers and chisels |
| 11.11 | ...Forming arcs and tangents
thereto | 42 | ..Millstone picks |
| 11.12 | ...Generation of arc or bevel by
two or more tools | 43 | ..Miners' picks |
| 11.13 | ...With compound motion of tool | | |
| 11.14 | ...Arc forming by swinging tool | | |
| 11.15 | ...Forming bevel | | |
| 11.16 | ...By swinging tool | | |
| 11.17 | ..Transverse swinging motion to
form planer surface | | |
| 11.18 | ..Peripheral grinding face | | |
| 11.19 | ..Radial grinding face | | |
| 11.2 | ..Hydraulic tool traversing means | | |
| 11.21 | ..Rectilinearly reciprocating
tool | | |
| 11.22 | ..Coolant supply | | |
| 11.23 | ..With compensator for tool wear | | |
| 12 | SAWING | | |
| 13.01 | .Rotary | | |
| 13.02 | ..Having internal cutting edge | | |
| 13.03 | ..With pivoted frame | | |
| 14 | ..Saw-support feed | | |
| 15 | ..Saw blades | | |
| 16.01 | .Reciprocating | | |
| 16.02 | ..Having saw with supply and
take-up means | | |
| 16.03 | ..Lever-operated saw | | |
| 16.04 | ..Angular cutting saws | | |
| 17 | ..Saw racks | | |
| 18 | ..Saw blades | | |
| 19 | .Oscillating | | |
- CROSS-REFERENCE ART COLLECTIONS**
- | | |
|-----|---------------------------------------|
| 901 | FORMING PIEZOELECTRIC CRYSTALS |
|-----|---------------------------------------|
- FOREIGN ART COLLECTIONS**
- | | |
|-----|--|
| FOR | CLASS-RELATED FOREIGN DOCUMENTS |
|-----|--|

