CPC COOPERATIVE PATENT CLASSIFICATION

D TEXTILES; PAPER

TEXTILES OR FLEXIBLE MATERIALS NOT OTHERWISE PROVIDED FOR

D03 WEAVING

3/00

3/02

3/04

5/00

5/02

5/04

5/06 5/065 Weavers' tools, e.g. knot-tying tools

• Shuttle-threading tools (threading devices in shuttles

Shuttles (swivel shuttles $\underline{D03D\ 31/00}$; shuttles for smallware looms $\underline{D03D\ 35/00}$; circular loom shuttles $\underline{D03D\ 37/00}$; selvedge shuttles $\underline{D03D\ 47/46}$)

. Reed and heald hooks

. Construction of shuttle body

. Dummy shuttles; Gripper shuttles

• • {for travelling-wave-shed looms}

D03J 5/20)

. . Shuttle tips

D03J AUXILIARY WEAVING APPARATUS; WEAVERS' TOOLS; SHUTTLES

WARNING

In this subclass non-limiting references (in the sense of paragraph 39 of the Guide to the IPC) may still be displayed in the scheme.

1/00	Auxiliary apparatus combined with or associated	5/08	. Supports for pirns, bobbins, or cops
	with looms	5/10	Pegs or spindles
1/001	• {Cloth or warp beam replacement}	5/12	· · · removable
1/002	• {Climatic conditioning or removing lint or dust}	5/14	• • pivoted
1/003	• {Devices for lubricating machine parts}	5/16	Bobbin clamps, e.g. for automatic bobbin-
1/004	• {Detection and repair of broken warp yarns}		changing loom shuttles
1/005	• {Displays or displaying data}	5/18	for coreless cops, i.e. shuttles having no peg or
1/006	• {Controlling a group of looms}		bobbin clamp
1/007	• {Fabric inspection on the loom and associated loom control}	5/20	 Devices in shuttles for threading (separate tools for threading shuttles <u>D03J 3/04</u>)
1/008	• {Cooling systems}	5/22	for self-threading, i.e. threading automatically
1/02	 for treating warp, e.g. cleaning, moistening 		when shuttle is picked
1/04	 for treating weft 	5/24	Tension devices
1/06	for treating fabric (cutting pile on the loom		
	<u>D03D 39/24</u>)	2700/00	Auxiliary apparatus associated with looms;
1/08	• • for slitting fabric		Weavening combined with other operations; Shuttles
1/10	 for indicating pattern to weaver 	2700/02	• Treatment of the weaving material on the loom, e.g.
1/12	 transferring bobbins between loom and winding 	2700/02	sizing, humidifying, cleaning
	station (bobbin-winding machines <u>B65H</u>)	2700/04	Efficiency control of looms
1/13	• for leasing warp (leasing in general <u>D02H 9/00</u>)	2700/04	Auxiliary devices for inspecting, counting or
1/14	 Apparatus for threading warp stop-motion droppers, 	2700/00	measuring
	healds, or reeds	2700/10	• Shuttles
1/16	Apparatus for joining warp ends (knot-tying tools	2700/12	for automatic bobbin changing
4.40	<u>D03J 3/00)</u>	2700/14	Gripper shuttles
1/18	• for joining, e.g. tying, a complete series of fresh	2700/16	• • with warp or weft stop motion
1/20	warp threads to the used warp threads	2,00,10	v v v viiii viiip or vieti stop inouon
1/20	 Measuring length of fabric or number of picks woven 		
1/22	. Temples		
1/223	• • {acting on the full width of cloth}		
1/226	• • {provided with a thread cutter}		
1/24			
1/24	 Mirrors or other arrangements for inspecting loom 		

CPC - 2024.05