

EUROPEAN PATENT OFFICE
U.S. PATENT AND TRADEMARK OFFICE

CPC NOTICE OF CHANGES 1181

DATE: JANUARY 1, 2022

PROJECT MP0527

The following classification changes will be effected by this Notice of Changes:

<u>Action</u>	<u>Subclass</u>	<u>Group(s)</u>
SCHEME:		
Warnings Deleted:	H01L	24/02, 24/18, 24/34, 24/50, 24/84, 24/93

Note: This project reflects the finalization of a portion of the reclassification indicated in MP0117, in particular, the subgroups of H01L24/00.

This Notice of Changes includes the following [Check the ones included]:

1. CLASSIFICATION SCHEME CHANGES

- A. New, Modified or Deleted Group(s)
- B. New, Modified or Deleted Warning(s)
- C. New, Modified or Deleted Note(s)
- D. New, Modified or Deleted Guidance Heading(s)

2. DEFINITIONS

- A. New or Modified Definitions (Full definition template)
- B. Modified or Deleted Definitions (Definitions Quick Fix)

3. REVISION CONCORDANCE LIST (RCL)

4. CHANGES TO THE CPC-TO-IPC CONCORDANCE LIST (CICL)

5. CHANGES TO THE CROSS-REFERENCE LIST (CRL)

CPC NOTICE OF CHANGES 1181

DATE: JANUARY 1, 2022

PROJECT MP0527

1. CLASSIFICATION SCHEME CHANGES

B. New, Modified or Deleted Warning(s)

SUBCLASS H01L – SEMICONDUCTOR DEVICES; ELECTRIC SOLID STATE DEVICES NOT OTHERWISE PROVIDED FOR (...)

<u>Type*</u>	<u>Location</u>	<u>Old Warning</u>	<u>New/Modified Warning</u>
D	H01L24/02	Groups H01L24/02 – H01L24/09 are incomplete pending reclassification of documents from groups H01L24/02 and H01L24/10. Groups H01L24/02 – H01L24/09 and H01L24/10 should be considered in order to perform a complete search.	Delete entire warnings
D	H01L24/18	Groups H01L24/18 – H01L24/25 are incomplete pending reclassification of documents from groups H01L24/18 and H01L24/82. Groups H01L24/18 – H01L24/25 and H01L24/82 should be considered in order to perform a complete search.	Delete entire warnings
D	H01L24/34	Groups H01L24/34 – H01L24/41 are incomplete pending reclassification of documents from groups H01L24/34, H01L24/01, H01L24/42, and H01L24/85. Groups H01L24/34 – H01L24/41 and H01L24/01, H01L24/42, H01L24/85 should be considered in order to perform a complete search.	Delete entire warnings
D	H01L24/50	Group H01L24/50 is incomplete pending reclassification of documents from group H01L24/86. Groups H01L24/50 and H01L24/86 should be considered in order to perform a complete search.	Delete entire warnings
D	H01L24/84	Group H01L24/84 is incomplete pending reclassification of documents from group H01L24/85. Group H01L24/84 and H01L24/85 should be considered in order to perform a complete search.	Delete entire warnings
D	H01L24/93	Group H01L24/93 is incomplete pending reclassification of documents from groups H01L24/80 – H01L24/90. Groups H01L24/93 and H01L24/80 – H01L24/90 should be considered in order to perform a complete search.	Delete entire warnings

*N = new warning, M = modified warning, D = deleted warning

NOTE: The “Location” column only requires the symbol PRIOR to the location of the warning. No further directions such as “before” or “after” are required.