

## CPC to IPC Concordance for Subclass B60K

CPC Group	IPC Group
B60K 1/00	B60K 1/00
B60K 2001/001	B60K 1/00
B60K 2001/003	B60K 1/00
B60K 2001/005	B60K 1/00
B60K 2001/006	B60K 1/00
B60K 2001/008	B60K 1/00
B60K 1/02	B60K 1/02
B60K 1/04	B60K 1/04
B60K 2001/0405	B60K 1/04
B60K 2001/0411	B60K 1/04
B60K 2001/0416	B60K 1/04
B60K 2001/0422	B60K 1/04
B60K 2001/0427	B60K 1/04
B60K 2001/0433	B60K 1/04
B60K 2001/0438	B60K 1/04
B60K 2001/0444	B60K 1/04
B60K 2001/045	B60K 1/04
B60K 2001/0455	B60K 1/04
B60K 2001/0461	B60K 1/04
B60K 2001/0466	B60K 1/04
B60K 2001/0472	B60K 1/04
B60K 2001/0477	B60K 1/04
B60K 2001/0483	B60K 1/04

<b>CPC Group</b>	<b>IPC Group</b>
<b>B60K 2001/0488</b>	<b>B60K 1/04</b>
<b>B60K 2001/0494</b>	<b>B60K 1/04</b>
<b>B60K 3/00</b>	<b>B60K 3/00</b>
<b>B60K 3/02</b>	<b>B60K 3/02</b>
<b>B60K 3/04</b>	<b>B60K 3/04</b>
<b>B60K 5/00</b>	<b>B60K 5/00</b>
<b>B60K 2005/003</b>	<b>B60K 5/00</b>
<b>B60K 2005/006</b>	<b>B60K 5/00</b>
<b>B60K 5/02</b>	<b>B60K 5/02</b>
<b>B60K 5/04</b>	<b>B60K 5/04</b>
<b>B60K 5/06</b>	<b>B60K 5/06</b>
<b>B60K 5/08</b>	<b>B60K 5/08</b>
<b>B60K 5/10</b>	<b>B60K 5/10</b>
<b>B60K 5/12</b>	<b>B60K 5/12</b>
<b>B60K 5/1208</b>	<b>B60K 5/12</b>
<b>B60K 5/1216</b>	<b>B60K 5/12</b>
<b>B60K 5/1225</b>	<b>B60K 5/12</b>
<b>B60K 5/1233</b>	<b>B60K 5/12</b>
<b>B60K 5/1241</b>	<b>B60K 5/12</b>
<b>B60K 5/125</b>	<b>B60K 5/12</b>
<b>B60K 5/1258</b>	<b>B60K 5/12</b>
<b>B60K 5/1266</b>	<b>B60K 5/12</b>
<b>B60K 5/1275</b>	<b>B60K 5/12</b>
<b>B60K 5/1283</b>	<b>B60K 5/12</b>

<b>CPC Group</b>	<b>IPC Group</b>
<b>B60K 5/1291</b>	<b>B60K 5/12</b>
<b>B60K 6/00</b>	<b>B60K 6/00</b>
<b>B60K 6/08</b>	<b>B60K 6/08</b>
<b>B60K 6/10</b>	<b>B60K 6/10</b>
<b>B60K 6/105</b>	<b>B60K 6/10</b>
<b>B60K 6/12</b>	<b>B60K 6/12</b>
<b>B60K 2006/123</b>	<b>B60K 6/12</b>
<b>B60K 2006/126</b>	<b>B60K 6/12</b>
<b>B60K 6/20</b>	<b>B60K 6/20</b>
<b>B60K 6/22</b>	<b>B60K 6/22</b>
<b>B60K 6/24</b>	<b>B60K 6/24</b>
<b>B60K 6/26</b>	<b>B60K 6/26</b>
<b>B60K 2006/262</b>	<b>B60K 6/26</b>
<b>B60K 2006/264</b>	<b>B60K 6/26</b>
<b>B60K 2006/266</b>	<b>B60K 6/26</b>
<b>B60K 2006/268</b>	<b>B60K 6/26</b>
<b>B60K 6/28</b>	<b>B60K 6/28</b>
<b>B60K 6/30</b>	<b>B60K 6/30</b>
<b>B60K 6/32</b>	<b>B60K 6/32</b>
<b>B60K 6/34</b>	<b>B60K 6/34</b>
<b>B60K 6/36</b>	<b>B60K 6/36</b>
<b>B60K 6/365</b>	<b>B60K 6/365</b>
<b>B60K 6/38</b>	<b>B60K 6/38</b>
<b>B60K 2006/381</b>	<b>B60K 6/38</b>

CPC Group	IPC Group
B60K 6/383	B60K 6/383
B60K 6/387	B60K 6/387
B60K 6/40	B60K 6/40
B60K 6/405	B60K 6/405
B60K 6/42	B60K 6/42
B60K 6/44	B60K 6/44
B60K 6/442	B60K 6/442
B60K 6/445	B60K 6/445
B60K 6/448	B60K 6/448
B60K 6/46	B60K 6/46
B60K 6/48	B60K 6/48
B60K 2006/4808	B60K 6/48
B60K 2006/4816	B60K 6/48
B60K 2006/4825	B60K 6/48
B60K 2006/4833	B60K 6/48
B60K 2006/4841	B60K 6/48
B60K 6/485	B60K 6/485
B60K 6/50	B60K 6/50
B60K 6/52	B60K 6/52
B60K 6/54	B60K 6/54
B60K 2006/541	B60K 6/54
B60K 2006/542	B60K 6/54
B60K 6/543	B60K 6/543
B60K 6/547	B60K 6/547

CPC Group	IPC Group
B60K 7/00	B60K 7/00
B60K 7/0007	B60K 7/00
B60K 7/0015	B60K 7/00
B60K 7/0023	B60K 7/00
B60K 2007/003	B60K 7/00
B60K 2007/0038	B60K 7/00
B60K 2007/0046	B60K 7/00
B60K 2007/0053	B60K 7/00
B60K 2007/0061	B60K 7/00
B60K 2007/0069	B60K 7/00
B60K 2007/0076	B60K 7/00
B60K 2007/0084	B60K 7/00
B60K 2007/0092	B60K 7/00
B60K 8/00	B60K 8/00
B60K 11/00	B60K 11/00
B60K 11/02	B60K 11/02
B60K 11/04	B60K 11/04
B60K 11/06	B60K 11/06
B60K 11/08	B60K 11/08
B60K 11/085	B60K 11/08
B60K 13/00	B60K 13/00
B60K 13/02	B60K 13/02
B60K 13/04	B60K 13/04
B60K 13/06	B60K 13/06

<b>CPC Group</b>	<b>IPC Group</b>
<b>B60K 15/00</b>	<b>B60K 15/00</b>
<b>B60K 15/01</b>	<b>B60K 15/01</b>
<b>B60K 15/013</b>	<b>B60K 15/01</b>
<b>B60K 2015/016</b>	<b>B60K 15/01</b>
<b>B60K 15/03</b>	<b>B60K 15/03</b>
<b>B60K 15/03006</b>	<b>B60K 15/03</b>
<b>B60K 2015/03013</b>	<b>B60K 15/03</b>
<b>B60K 2015/03019</b>	<b>B60K 15/03</b>
<b>B60K 2015/03026</b>	<b>B60K 15/03</b>
<b>B60K 2015/03032</b>	<b>B60K 15/03</b>
<b>B60K 2015/03039</b>	<b>B60K 15/03</b>
<b>B60K 2015/03046</b>	<b>B60K 15/03</b>
<b>B60K 2015/03052</b>	<b>B60K 15/03</b>
<b>B60K 2015/03059</b>	<b>B60K 15/03</b>
<b>B60K 2015/03065</b>	<b>B60K 15/03</b>
<b>B60K 2015/03072</b>	<b>B60K 15/03</b>
<b>B60K 2015/03078</b>	<b>B60K 15/03</b>
<b>B60K 2015/03085</b>	<b>B60K 15/03</b>
<b>B60K 2015/03092</b>	<b>B60K 15/03</b>
<b>B60K 2015/03098</b>	<b>B60K 15/03</b>
<b>B60K 2015/03105</b>	<b>B60K 15/03</b>
<b>B60K 2015/03111</b>	<b>B60K 15/03</b>
<b>B60K 2015/03118</b>	<b>B60K 15/03</b>
<b>B60K 2015/03125</b>	<b>B60K 15/03</b>

<b>CPC Group</b>	<b>IPC Group</b>
<b>B60K 2015/03131</b>	<b>B60K 15/03</b>
<b>B60K 2015/03138</b>	<b>B60K 15/03</b>
<b>B60K 2015/03144</b>	<b>B60K 15/03</b>
<b>B60K 2015/03151</b>	<b>B60K 15/03</b>
<b>B60K 2015/03157</b>	<b>B60K 15/03</b>
<b>B60K 2015/03164</b>	<b>B60K 15/03</b>
<b>B60K 2015/03171</b>	<b>B60K 15/03</b>
<b>B60K 15/03177</b>	<b>B60K 15/03</b>
<b>B60K 2015/03184</b>	<b>B60K 15/03</b>
<b>B60K 2015/0319</b>	<b>B60K 15/03</b>
<b>B60K 2015/03197</b>	<b>B60K 15/03</b>
<b>B60K 2015/03203</b>	<b>B60K 15/03</b>
<b>B60K 2015/0321</b>	<b>B60K 15/03</b>
<b>B60K 2015/03217</b>	<b>B60K 15/03</b>
<b>B60K 2015/03223</b>	<b>B60K 15/03</b>
<b>B60K 2015/0323</b>	<b>B60K 15/03</b>
<b>B60K 2015/03236</b>	<b>B60K 15/03</b>
<b>B60K 2015/03243</b>	<b>B60K 15/03</b>
<b>B60K 2015/0325</b>	<b>B60K 15/03</b>
<b>B60K 2015/03256</b>	<b>B60K 15/03</b>
<b>B60K 2015/03263</b>	<b>B60K 15/03</b>
<b>B60K 2015/03269</b>	<b>B60K 15/03</b>
<b>B60K 2015/03276</b>	<b>B60K 15/03</b>
<b>B60K 2015/03282</b>	<b>B60K 15/03</b>

<b>CPC Group</b>	<b>IPC Group</b>
<b>B60K 2015/03289</b>	<b>B60K 15/03</b>
<b>B60K 2015/03296</b>	<b>B60K 15/03</b>
<b>B60K 2015/03302</b>	<b>B60K 15/03</b>
<b>B60K 2015/03309</b>	<b>B60K 15/03</b>
<b>B60K 2015/03315</b>	<b>B60K 15/03</b>
<b>B60K 2015/03322</b>	<b>B60K 15/03</b>
<b>B60K 2015/03328</b>	<b>B60K 15/03</b>
<b>B60K 2015/03335</b>	<b>B60K 15/03</b>
<b>B60K 2015/03342</b>	<b>B60K 15/03</b>
<b>B60K 2015/03348</b>	<b>B60K 15/03</b>
<b>B60K 2015/03355</b>	<b>B60K 15/03</b>
<b>B60K 2015/03361</b>	<b>B60K 15/03</b>
<b>B60K 2015/03368</b>	<b>B60K 15/03</b>
<b>B60K 2015/03375</b>	<b>B60K 15/03</b>
<b>B60K 2015/03381</b>	<b>B60K 15/03</b>
<b>B60K 2015/03388</b>	<b>B60K 15/03</b>
<b>B60K 2015/03394</b>	<b>B60K 15/03</b>
<b>B60K 2015/03401</b>	<b>B60K 15/03</b>
<b>B60K 2015/03407</b>	<b>B60K 15/03</b>
<b>B60K 2015/03414</b>	<b>B60K 15/03</b>
<b>B60K 2015/03421</b>	<b>B60K 15/03</b>
<b>B60K 2015/03427</b>	<b>B60K 15/03</b>
<b>B60K 2015/03434</b>	<b>B60K 15/03</b>
<b>B60K 2015/0344</b>	<b>B60K 15/03</b>

CPC Group	IPC Group
B60K 2015/03447	B60K 15/03
B60K 2015/03453	B60K 15/03
B60K 2015/0346	B60K 15/03
B60K 2015/03467	B60K 15/03
B60K 2015/03473	B60K 15/03
B60K 2015/0348	B60K 15/03
B60K 2015/03486	B60K 15/03
B60K 2015/03493	B60K 15/03
B60K 15/035	B60K 15/035
B60K 15/03504	B60K 15/035
B60K 2015/03509	B60K 15/035
B60K 2015/03514	B60K 15/035
B60K 15/03519	B60K 15/035
B60K 2015/03523	B60K 15/035
B60K 2015/03528	B60K 15/035
B60K 2015/03533	B60K 15/035
B60K 2015/03538	B60K 15/035
B60K 2015/03542	B60K 15/035
B60K 2015/03547	B60K 15/035
B60K 2015/03552	B60K 15/035
B60K 2015/03557	B60K 15/035
B60K 2015/03561	B60K 15/035
B60K 2015/03566	B60K 15/035
B60K 2015/03571	B60K 15/035

CPC Group	IPC Group
B60K 2015/03576	B60K 15/035
B60K 2015/0358	B60K 15/035
B60K 2015/03585	B60K 15/035
B60K 2015/0359	B60K 15/035
B60K 2015/03595	B60K 15/035
B60K 15/04	B60K 15/04
B60K 15/0403	B60K 15/04
B60K 15/0406	B60K 15/04
B60K 15/0409	B60K 15/04
B60K 2015/0412	B60K 15/04
B60K 2015/0416	B60K 15/04
B60K 2015/0419	B60K 15/04
B60K 2015/0422	B60K 15/04
B60K 2015/0425	B60K 15/04
B60K 2015/0429	B60K 15/04
B60K 2015/0432	B60K 15/04
B60K 2015/0435	B60K 15/04
B60K 2015/0438	B60K 15/04
B60K 2015/0441	B60K 15/04
B60K 2015/0445	B60K 15/04
B60K 2015/0448	B60K 15/04
B60K 2015/0451	B60K 15/04
B60K 2015/0454	B60K 15/04
B60K 2015/0458	B60K 15/04

<b>CPC Group</b>	<b>IPC Group</b>
<b>B60K 2015/0461</b>	<b>B60K 15/04</b>
<b>B60K 2015/0464</b>	<b>B60K 15/04</b>
<b>B60K 2015/0467</b>	<b>B60K 15/04</b>
<b>B60K 2015/047</b>	<b>B60K 15/04</b>
<b>B60K 2015/0474</b>	<b>B60K 15/04</b>
<b>B60K 2015/0477</b>	<b>B60K 15/04</b>
<b>B60K 2015/048</b>	<b>B60K 15/04</b>
<b>B60K 2015/0483</b>	<b>B60K 15/04</b>
<b>B60K 2015/0487</b>	<b>B60K 15/04</b>
<b>B60K 2015/049</b>	<b>B60K 15/04</b>
<b>B60K 2015/0493</b>	<b>B60K 15/04</b>
<b>B60K 2015/0496</b>	<b>B60K 15/04</b>
<b>B60K 15/05</b>	<b>B60K 15/05</b>
<b>B60K 2015/0507</b>	<b>B60K 15/05</b>
<b>B60K 2015/0515</b>	<b>B60K 15/05</b>
<b>B60K 2015/0523</b>	<b>B60K 15/05</b>
<b>B60K 2015/053</b>	<b>B60K 15/05</b>
<b>B60K 2015/0538</b>	<b>B60K 15/05</b>
<b>B60K 2015/0546</b>	<b>B60K 15/05</b>
<b>B60K 2015/0553</b>	<b>B60K 15/05</b>
<b>B60K 2015/0561</b>	<b>B60K 15/05</b>
<b>B60K 2015/0569</b>	<b>B60K 15/05</b>
<b>B60K 2015/0576</b>	<b>B60K 15/05</b>
<b>B60K 2015/0584</b>	<b>B60K 15/05</b>

CPC Group	IPC Group
B60K 2015/0592	B60K 15/05
B60K 15/06	B60K 15/06
B60K 15/061	B60K 15/06
B60K 2015/062	B60K 15/06
B60K 15/063	B60K 15/063
B60K 2015/0631	B60K 15/063
B60K 2015/0632	B60K 15/063
B60K 2015/0633	B60K 15/063
B60K 2015/0634	B60K 15/063
B60K 2015/0635	B60K 15/063
B60K 2015/0636	B60K 15/063
B60K 2015/0637	B60K 15/063
B60K 2015/0638	B60K 15/063
B60K 2015/0639	B60K 15/063
B60K 15/067	B60K 15/067
B60K 2015/0675	B60K 15/067
B60K 15/07	B60K 15/07
B60K 15/073	B60K 15/073
B60K 15/077	B60K 15/077
B60K 2015/0772	B60K 15/077
B60K 2015/0775	B60K 15/077
B60K 2015/0777	B60K 15/077
B60K 15/10	B60K 15/10
B60K 16/00	B60K 16/00

CPC Group	IPC Group
B60K 2016/003	B60K 16/00
B60K 2016/006	B60K 16/00
B60K 17/00	B60K 17/00
B60K 17/02	B60K 17/02
B60K 17/04	B60K 17/04
B60K 17/043	B60K 17/04
B60K 17/046	B60K 17/04
B60K 17/06	B60K 17/06
B60K 17/08	B60K 17/08
B60K 17/10	B60K 17/10
B60K 17/105	B60K 17/10
B60K 17/12	B60K 17/12
B60K 17/14	B60K 17/14
B60K 17/145	B60K 17/14
B60K 17/16	B60K 17/16
B60K 17/165	B60K 17/16
B60K 17/18	B60K 17/16
B60K 17/20	B60K 17/16
B60K 17/22	B60K 17/22
B60K 17/24	B60K 17/24
B60K 17/26	B60K 17/26
B60K 17/28	B60K 17/28
B60K 17/30	B60K 17/30
B60K 17/303	B60K 17/30

CPC Group	IPC Group
B60K 17/306	B60K 17/30
B60K 17/32	B60K 17/32
B60K 17/34	B60K 17/34
B60K 17/342	B60K 17/342
B60K 17/344	B60K 17/344
B60K 17/346	B60K 17/346
B60K 17/3462	B60K 17/346
B60K 17/3465	B60K 17/346
B60K 17/3467	B60K 17/346
B60K 17/348	B60K 17/348
B60K 17/35	B60K 17/35
B60K 17/3505	B60K 17/35
B60K 17/351	B60K 17/35
B60K 17/3515	B60K 17/35
B60K 17/352	F16H 48/30
B60K 17/354	B60K 17/354
B60K 17/356	B60K 17/356
B60K 17/358	B60K 17/34
B60K 17/36	B60K 17/36
B60K 20/00	B60K 20/00
B60K 20/02	B60K 20/02
B60K 20/04	B60K 20/04
B60K 20/06	B60K 20/06
B60K 20/08	B60K 20/08

CPC Group	IPC Group
B60K 20/14	B60K 20/02
B60K 23/00	B60K 23/00
B60K 2023/005	B60K 23/00
B60K 23/02	B60K 23/02
B60K 2023/025	B60K 23/02
B60K 23/04	B60K 23/04
B60K 2023/043	B60K 23/04
B60K 2023/046	B60K 23/04
B60K 23/06	B60K 23/06
B60K 23/08	B60K 23/08
B60K 23/0808	B60K 23/08
B60K 2023/0816	B60K 23/08
B60K 2023/0825	B60K 23/08
B60K 2023/0833	B60K 23/08
B60K 2023/0841	B60K 23/08
B60K 2023/085	B60K 23/08
B60K 2023/0858	B60K 23/08
B60K 2023/0866	B60K 23/08
B60K 2023/0875	B60K 23/08
B60K 2023/0883	B60K 23/08
B60K 2023/0891	B60K 23/08
B60K 25/00	B60K 25/00
B60K 2025/005	B60K 25/00
B60K 25/02	B60K 25/02

<b>CPC Group</b>	<b>IPC Group</b>
<b>B60K 2025/022</b>	<b>B60K 25/02</b>
<b>B60K 2025/024</b>	<b>B60K 25/02</b>
<b>B60K 2025/026</b>	<b>B60K 25/02</b>
<b>B60K 2025/028</b>	<b>B60K 25/02</b>
<b>B60K 25/04</b>	<b>B60K 25/04</b>
<b>B60K 25/06</b>	<b>B60K 25/06</b>
<b>B60K 2025/065</b>	<b>B60K 25/06</b>
<b>B60K 25/08</b>	<b>B60K 25/08</b>
<b>B60K 25/10</b>	<b>B60K 25/10</b>
<b>B60K 2025/103</b>	<b>B60K 25/10</b>
<b>B60K 2025/106</b>	<b>B60K 25/10</b>
<b>B60K 26/00</b>	<b>B60K 26/00</b>
<b>B60K 26/02</b>	<b>B60K 26/02</b>
<b>B60K 26/021</b>	<b>B60K 26/02</b>
<b>B60K 2026/022</b>	<b>B60K 26/02</b>
<b>B60K 2026/023</b>	<b>B60K 26/02</b>
<b>B60K 2026/024</b>	<b>B60K 26/02</b>
<b>B60K 2026/025</b>	<b>B60K 26/02</b>
<b>B60K 2026/026</b>	<b>B60K 26/02</b>
<b>B60K 2026/027</b>	<b>B60K 26/02</b>
<b>B60K 2026/028</b>	<b>B60K 26/02</b>
<b>B60K 2026/029</b>	<b>B60K 26/02</b>
<b>B60K 26/04</b>	<b>B60K 26/04</b>
<b>B60K 2026/043</b>	<b>B60K 26/04</b>

<b>CPC Group</b>	<b>IPC Group</b>
<b>B60K 2026/046</b>	<b>B60K 26/04</b>
<b>B60K 28/00</b>	<b>B60K 28/00</b>
<b>B60K 2028/003</b>	<b>B60K 28/00</b>
<b>B60K 2028/006</b>	<b>B60K 28/00</b>
<b>B60K 28/02</b>	<b>B60K 28/02</b>
<b>B60K 28/04</b>	<b>B60K 28/04</b>
<b>B60K 28/06</b>	<b>B60K 28/06</b>
<b>B60K 28/063</b>	<b>B60K 28/06</b>
<b>B60K 28/066</b>	<b>B60K 28/06</b>
<b>B60K 28/08</b>	<b>B60K 28/08</b>
<b>B60K 28/10</b>	<b>B60K 28/10</b>
<b>B60K 28/12</b>	<b>B60K 28/12</b>
<b>B60K 28/14</b>	<b>B60K 28/14</b>
<b>B60K 28/16</b>	<b>B60K 28/16</b>
<b>B60K 28/165</b>	<b>B60K 28/16</b>
<b>B60K 31/00</b>	<b>B60K 31/00</b>
<b>B60K 31/0008</b>	<b>B60K 31/00</b>
<b>B60K 2031/0016</b>	<b>B60K 31/00</b>
<b>B60K 2031/0025</b>	<b>B60K 31/00</b>
<b>B60K 2031/0033</b>	<b>B60K 31/00</b>
<b>B60K 2031/0041</b>	<b>B60K 31/00</b>
<b>B60K 2031/005</b>	<b>B60K 31/00</b>
<b>B60K 31/0058</b>	<b>B60K 31/00</b>
<b>B60K 31/0066</b>	<b>B60K 31/00</b>

<b>CPC Group</b>	<b>IPC Group</b>
<b>B60K 31/0075</b>	<b>B60K 31/00</b>
<b>B60K 31/0083</b>	<b>B60K 31/00</b>
<b>B60K 2031/0091</b>	<b>B60K 31/00</b>
<b>B60K 31/02</b>	<b>B60K 31/02</b>
<b>B60K 31/04</b>	<b>B60K 31/04</b>
<b>B60K 31/042</b>	<b>B60K 31/04</b>
<b>B60K 31/045</b>	<b>B60K 31/04</b>
<b>B60K 31/047</b>	<b>B60K 31/04</b>
<b>B60K 31/06</b>	<b>B60K 31/06</b>
<b>B60K 31/08</b>	<b>B60K 31/08</b>
<b>B60K 31/10</b>	<b>B60K 31/10</b>
<b>B60K 31/102</b>	<b>B60K 31/10</b>
<b>B60K 31/105</b>	<b>B60K 31/10</b>
<b>B60K 31/107</b>	<b>B60K 31/10</b>
<b>B60K 31/12</b>	<b>B60K 31/12</b>
<b>B60K 31/14</b>	<b>B60K 31/14</b>
<b>B60K 31/16</b>	<b>B60K 31/16</b>
<b>B60K 31/18</b>	<b>B60K 31/18</b>
<b>B60K 31/185</b>	<b>B60K 31/18</b>
<b>B60K 35/00</b>	<b>B60K 35/00</b>
<b>B60K 37/00</b>	<b>B60K 37/00</b>
<b>B60K 37/02</b>	<b>B60K 37/02</b>
<b>B60K 37/04</b>	<b>B60K 37/04</b>
<b>B60K 37/06</b>	<b>B60K 37/06</b>

CPC Group	IPC Group
B60K 2310/00	—
B60K 2310/20	—
B60K 2310/22	—
B60K 2310/24	—
B60K 2310/242	—
B60K 2310/244	—
B60K 2310/246	—
B60K 2310/248	—
B60K 2310/26	—
B60K 2310/262	—
B60K 2310/264	—
B60K 2310/266	—
B60K 2310/268	—
B60K 2310/28	—
B60K 2310/30	—
B60K 2350/00	—
B60K 2350/10	—
B60K 2350/1004	—
B60K 2350/1008	—
B60K 2350/1012	—
B60K 2350/1016	—
B60K 2350/102	—
B60K 2350/1024	—
B60K 2350/1028	—

CPC Group	IPC Group
B60K 2350/1032	—
B60K 2350/1036	—
B60K 2350/104	—
B60K 2350/1044	—
B60K 2350/1048	—
B60K 2350/1052	—
B60K 2350/1056	—
B60K 2350/106	—
B60K 2350/1064	—
B60K 2350/1068	—
B60K 2350/1072	—
B60K 2350/1076	—
B60K 2350/108	—
B60K 2350/1084	—
B60K 2350/1088	—
B60K 2350/1092	—
B60K 2350/1096	—
B60K 2350/20	—
B60K 2350/2004	—
B60K 2350/2008	—
B60K 2350/2013	—
B60K 2350/2017	—
B60K 2350/2021	—
B60K 2350/2026	—

CPC Group	IPC Group
B60K 2350/203	—
B60K 2350/2034	—
B60K 2350/2039	—
B60K 2350/2043	—
B60K 2350/2047	—
B60K 2350/2052	—
B60K 2350/2056	—
B60K 2350/206	—
B60K 2350/2065	—
B60K 2350/2069	—
B60K 2350/2073	—
B60K 2350/2078	—
B60K 2350/2082	—
B60K 2350/2086	—
B60K 2350/2091	—
B60K 2350/2095	—
B60K 2350/30	—
B60K 2350/302	—
B60K 2350/305	—
B60K 2350/307	—
B60K 2350/35	—
B60K 2350/352	—
B60K 2350/355	—
B60K 2350/357	—

CPC Group	IPC Group
B60K 2350/40	—
B60K 2350/401	—
B60K 2350/402	—
B60K 2350/403	—
B60K 2350/405	—
B60K 2350/406	—
B60K 2350/407	—
B60K 2350/408	—
B60K 2350/90	—
B60K 2350/901	—
B60K 2350/903	—
B60K 2350/905	—
B60K 2350/906	—
B60K 2350/908	—
B60K 2350/92	—
B60K 2350/921	—
B60K 2350/922	—
B60K 2350/924	—
B60K 2350/925	—
B60K 2350/927	—
B60K 2350/928	—
B60K 2350/94	—
B60K 2350/941	—
B60K 2350/943	—

CPC Group	IPC Group
B60K 2350/945	—
B60K 2350/946	—
B60K 2350/948	—
B60K 2350/96	—
B60K 2350/962	—
B60K 2350/965	—
B60K 2350/967	—
B60K 2700/00	—
B60K 2700/02	—
B60K 2702/00	—
B60K 2702/02	—
B60K 2702/04	—
B60K 2702/06	—
B60K 2702/08	—
B60K 2702/10	—
B60K 2702/12	—
B60K 2702/14	—
B60K 2702/16	—
B60K 2702/18	—
B60K 2702/20	—
B60K 2704/00	—
B60K 2704/02	—
B60K 2704/04	—